




All Defects		Lot 11/Tract 6164		
<div><div></div>Anlin Windows</div>				
Code: ZZ_2661		Location:	Description: Damaged window frame in bed 2	Incomplete
Category: Windows		Type:		
Partner: Anlin Windows				
<div><div></div>Cabinet Connection</div>				
Code: ZZ_2664		Location:	Description: Missing knobs on drawers in bath 2	Incomplete
Category: Cabinets		Type:		
Partner: Cabinet Connection				
Code: ZZ_2665		Location:	Description: Missing twe in bath 2	Incomplete
Category: Cabinets		Type:		
Partner: Cabinet Connection				
Code: ZZ_2666		Location:	Description: Cabinet touch up in bath 2	Incomplete
Category: Cabinets		Type:		
Partner: Cabinet Connection				
Code: ZZ_2667		Location:	Description: Adjust drawers in bath 2	Incomplete
Category: Cabinets		Type:		
Partner: Cabinet Connection				
Code: ZZ_2672		Location:	Description: Cabinet touch up in laundry room.	Incomplete
Category: Cabinets		Type:		
Partner: Cabinet Connection				
Code: ZZ_2673		Location:	Description: Adjust cabinets in laundry room	Incomplete
Category: Cabinets		Type:		
Partner: Cabinet Connection				
Code: ZZ_2674		Location:	Description: Install twe in laundry room	Incomplete
Category: Cabinets		Type:		
Partner: Cabinet Connection				

Code: ZZ_2675	Location:	Description: Missing knobs in all drawers in kitchen	Incomplete
Category: Cabinets	Type:		
Partner: Cabinet Connection			
Code: ZZ_2676	Location:	Description: Missing twe in kitchen	Incomplete
Category: Cabinets	Type:		
Partner: Cabinet Connection			
Code: ZZ_2679	Location:	Description: Missing knobs on drawers in master bathroom	Incomplete
Category: Cabinets	Type:		
Partner: Cabinet Connection			
Code: ZZ_2680	Location:	Description: Twe missing in master bathroom	Incomplete
Category: Cabinets	Type:		
Partner: Cabinet Connection			
 Elia Painting			
Code: ZZ_2662	Location:	Description: Paint baseboards in bed 2	Incomplete
Category: Paint	Type:		
Partner: Elia Painting			
Code: ZZ_2671	Location:	Description: Paint base in bed 3	Incomplete
Category: Paint	Type:		
Partner: Elia Painting			
Code: ZZ_2681	Location:	Description: Paint baseboards Throughout home	Incomplete
Category: Paint	Type:		
Partner: Elia Painting			
 Ideal Custom Tile			
Code: ZZ_2668	Location:	Description: Grout crack in bath 2	Incomplete
Category: Tile	Type:		
Partner: Ideal Custom Tile			
 Landscape Connection			

Code: ZZ_2682	Location:		
Category: Landscaping	Type:	Description: Landscape missing	Incomplete
Partner: Landscape Connection			
Code: ZZ_2683	Location:		
Category: Landscaping	Type:	Description: Connect gutter downspout	Incomplete
Partner: Landscape Connection			
<div><div></div>Matthews Quality Construction</div>			
Code: ZZ_2660	Location:		
Category: Millwork	Type:	Description: Damaged baseboard in bed 2	Incomplete
Partner: Matthews Quality Construction			
Code: ZZ_2663	Location:		
Category: Millwork	Type:	Description: Damaged baseboard in hall	Incomplete
Partner: Matthews Quality Construction			
Code: ZZ_2670	Location:		
Category: Millwork	Type:	Description: Missing door stoppers in home	Incomplete
Partner: Matthews Quality Construction			
Code: ZZ_2677	Location:		
Category: Millwork	Type:	Description: Baseboard damaged in great room	Incomplete
Partner: Matthews Quality Construction			
<div><div></div>Ohanians Drywall</div>			
Code: ZZ_2669	Location:		
Category: Drywall	Type:	Description: Dent in drywall in bath 2	Incomplete
Partner: Ohanians Drywall			

Code: ZZ_2678

Category: Drywall

Partner: Ohanians Drywall

Location:

Type:

Description: Ding in drywall in hall

Incomplete