De Young Properties

be roung Propertie			
Lot 350/Tract 0273	Items: 28	CH Items: 2	Checklist Inspections: 195
Anlin Windows			
Code: J_132			
Category: Windows	Location: Bedroom 1	Description: Missing screen	Incomplete
Partner: Anlin Windows	Type: Window missing a screen		
Cabinet Connection	on		
Code: B_188			
Category: Cabinets	Location: Kitchen	Description: Missing Twe	Incomplete
Partner: Cabinet Connection	Type: Cabinet missing trim or other parts	in kitchen	
Code: B_189		Description Chair	
Category: Cabinets	Location: Kitchen	Description: Stain coming off on corners	Incomplete
Partner: Cabinet Connection	Type: Cabinets have scratches, chips, and/or cracks	and edges of doors and drawers in kitchen	
Code: B_190	Location: Kitchen		
Category: Cabinets		Description: Scratches	Incomplete
Partner: Cabinet Connection	Type: Cabinets have scratches, chips, and/or cracks	on fridge surround	
Code: B_191	Location: Kitchen	Doscription: Stain	
Category: Cabinets		Description: Stain coming off on corners of drawers left of oven	Incomplete
Partner: Cabinet Connection	Type: Cabinets have scratches, chips, and/or cracks	lowers	
Code: B_192	Location: Kitchen	Description: Stain	
Category: Cabinets		coming off on corners of doors to the left of	Incomplete
Partner: Cabinet Connection	Type: Cabinets have scratches, chips, and/or cracks	microwave	
Code: B_193	Location: Kitchen	Description: Stain	
Category: Cabinets		Description: Stain coming off and	Incomplete
Partner: Cabinet Connection	Type: Cabinets have scratches, chips, and/or cracks	scratches on drawers to the right of oven	

Lot 350/Tract 0273	Items: 28	CH Items: 2	Checklist Inspections: 195	
Code: B_194				
Category: Cabinets	Location: Great Room	Description: Scratches on top of cabinet left of	Incomplete	
Partner: Cabinet Connection	Type: Scratches	fireplace		
Code: B_195				
Category: Cabinets	Location: Bathroom 1	Description: Missing	Incomplete	
Partner: Cabinet Connection	Type: Cabinet missing trim or other parts	twe		
Code: B_196	Location: Bathroom 1			
Category: Cabinets	Type: Scratches/chips/cracks/gouges in	Description: Scratches on faces of doors left	Incomplete	
Partner: Cabinet Connection	cabinets	side vanity		
Code: B_197	Location: Bathroom 1			
Category: Cabinets	Type: Scratches/chips/cracks/gouges in	Description: Scratches on drawers in center	Incomplete	
Partner: Cabinet Connection	cabinets	on drawers in center		
Code: B_198	Location: Bathroom 1	Description: Drawers not aligned	Incomplete	
Category: Cabinets	Type: Issues with cabinet drawers and/or			
Partner: Cabinet Connection	doors functionality	angricu		
Code: B_199				
Category: Cabinets	Location: Bathroom 2	Description: Missing twe	Incomplete	
Partner: Cabinet Connection	Type: Cabinet missing trim or other parts	CVVC		
Code: B_200				
Category: Cabinets	Location: Bathroom 2	Description: Missing scribe	Incomplete	
Partner: Cabinet Connection	Type: Cabinet missing trim or other parts	SCHUE		
Elia Painting				
Code: Z_008				
Category: Paint	Location: Hallway	Description: Paint touch up on doors to laundry	Incomplete	
Partner: Elia Painting	Type: Touch up	room		

Location: Great Room Category: Low Description: Finish low Incomplete Voltage Electrical Type: Low voltage/data jacks missing or voltage above fireplace

not functional

Incomplete

Code: J 131 Location: Bedroom 1

Category: Low Description: Finish low Voltage Electrical Type: Low voltage/data jacks missing or voltage in master

not functional

Partner: LinkUs

Partner: LinkUs

Lot 350/Tract 0273	Items: 28	CH Items: 2	Checklist Inspections: 195			
Code: J_134 Category: Electrical Partner: LinkUs	Location: Bathroom 1 Type: Light fixtures, or pieces of light fixtures, are missing	Description: Finish link us box	Incomplete			
Code: J_136 Category: Electrical Partner: LinkUs	Location: Exterior Type: Light fixture, or pieces of light fixture, are missing	Description: Change out door bell to nest doorbell	Incomplete			
Quality Plumbing						
Code: J_135 Category: Plumbing Partner: Quality Plumbing	Location: Bathroom 2 Type: Defect(s) in Bath/Shower fitter/surround	Description: Rust on bottom of tub scratches on edges	Incomplete			
Tri Valley Plasteri	Tri Valley Plastering & Drywall					
Code: F_033 Category: Stucco Partner: Tri Valley Plastering & Drywall	Location: Exterior Type: Chip/crack/gouge	Description: Touch up by front pillar	Incomplete			
Code: F_034 Category: Stucco Partner: Tri Valley Plastering & Drywall	Location: Exterior Type: Chip/crack/gouge	Description: Touch up around garage door	Incomplete			
Code: F_035 Category: Stucco Partner: Tri Valley Plastering & Drywall	Location: Exterior Type: Chip/crack/gouge	Description: Stucco touch up by carriage light	Incomplete			
Code: F_036 Category: Stucco Partner: Tri Valley Plastering & Drywall	Location: Exterior Type: Chip/crack/gouge	Description: Stucco cracks inside of home	Incomplete			