

All Defects

Lot 54/Tract 6102

Anlin Windows

Code: ZZ_245	Location: Dining Nook		
Category: Windows		Description: Torn window screen	Incomplete
Partner: Anlin Windows	Type:		

Cabinet Connection


Code: ZZ_246	Location:		
Category: Cabinets	Type:	Description: Misc scratches on kitchen cabinets	Incomplete
Partner: Cabinet Connection			

Code: ZZ_251	Location:		
Category: Cabinets	Type:	Description: Cabinet scratches in master bed closet	Incomplete
Partner: Cabinet Connection			


Everlast Paint

Code: ZZ_248	Location:		
Category: Paint	Type:	Description: Pain in hall by garage door	Incomplete
Partner: Everlast Paint			

Code: ZZ_253	Location:		
Category: Paint	Type:	Description: Paint stair well by hand rail	Incomplete
Partner: Everlast Paint			

Matthews Quality Construction

Code: ZZ_252	Location:		
Category: Millwork	Type:	Description: Baseboard chip in bed 3	Incomplete
Partner: Matthews Quality Construction			

Quality Plumbing

All Defects		Lot 54/Tract 6102		
Code: ZZ_247		Location: Type:	Description: Missing shower head in bath 3	Incomplete
Category: Plumbing				
Partner: Quality Plumbing				
<div><div></div> Tile Interiors</div>				
Code: ZZ_249		Location: Type:	Description: Grout tile kick in bath 3	Incomplete
Category: Tile				
Partner: Tile Interiors				
Code: ZZ_250		Location: Type:	Description: Grout tile kick master bath	Incomplete
Category: Tile				
Partner: Tile Interiors				
Code: ZZ_254		Location: Type:	Description: Grout tile by stairs	Incomplete
Category: Tile				
Partner: Tile Interiors				