

Lot 348/Tract 0273	Items: 14	CH Items: 1	Checklist Inspections: 0
--------------------	-----------	-------------	--------------------------

<div><div></div>Elia Painting</div>			
Code: ZZ_1308	Location: Bedroom 2	Description: Paint touch up not completed	Complete
Category: Paint	Type: Touch-up required		
Partner: Elia Painting			
Code: ZZ_1309	Location: Bathroom 3	Description: Paint touch up required	Complete
Category: Paint	Type: Touch-up required		
Partner: Elia Painting			
Code: ZZ_1310	Location: Bedroom 2	Description: Touch up required	Complete
Category: Paint	Type: Touch-up required		
Partner: Elia Painting			
Code: ZZ_1312	Location: Bathroom 1	Description: Paint touch up	Complete
Category: Paint	Type: Touch-up required		
Partner: Elia Painting			
Code: ZZ_1313	Location: Bedroom 1	Description: Touch up needed painters in right now	Complete
Category: Paint	Type: Touch-up required		
Partner: Elia Painting			
Code: ZZ_1316	Location: Kitchen	Description: Touch up required	Complete
Category: Paint	Type: Touch-up required		
Partner: Elia Painting			
<div><div></div>Ferguson</div>			
Code: ZZ_1314	Location: Kitchen	Description: Dishwasher not installed	<div>CRITICAL</div> Complete
Category: Appliances	Type: Appliance(s) missing		
Partner: Ferguson			
<div><div></div>Fresno Shower Door & Mirror</div>			

Lot 348/Tract 0273		Items: 14	CH Items: 1	Checklist Inspections: 0
Code: ZZ_1311				
Category: Shower Door & Mirror	Location: Bathroom 1	Type: Installation issue or defect	Description: Missing shower door	Complete
Partner: Fresno Shower Door & Mirror				
<div><div></div>MV Style Electric</div>				
Code: ZZ_1303				
Category: Electrical	Location: Exterior	Type: Light fixture, or pieces of light fixture, are missing	Description: Missing carriage light on left of garage	Complete
Partner: MV Style Electric				
Code: ZZ_1304				
Category: Electrical	Location: Exterior	Type: Light fixture, or pieces of light fixture, are missing	Description: Missing doorbell	Complete
Partner: MV Style Electric				
<div><div></div>Ohanians Drywall</div>				
Code: ZZ_1315				
Category: Drywall	Location: Kitchen	Type: Drywall texture issues	Description: Drywall touch up in kitchen	Complete
Partner: Ohanians Drywall				
<div><div></div>Premier Door</div>				
Code: ZZ_1306				
Category: Millwork	Location: Stairwell	Type: Door trim has chip, gash, gouge, cut too short near flooring or is missing	Description: Missing window sill in stairwell	Complete
Partner: Premier Door				
Code: ZZ_1307				
Category: Millwork	Location: Bedroom 2	Type: Baseboards missing or have chips/gouges	Description: Chunk of baseboard gash	Complete
Partner: Premier Door				
<div><div></div>Tri Valley Plastering & Drywall</div>				

Code: ZZ_1305

Category: Stucco

Partner: Tri Valley
Plastering & Drywall

Location: Exterior

Type: Chip/crack/gouge

Description: Large chunk of
stucco missing on front
pillar

Complete