

All Defects		Lot 129/Tract 0273		
<div><div></div>Anlin Windows</div>				
Code: ZZ_3212		Location:		
Category: Windows		Type:	Description: Window in great room will not open	Incomplete
Partner: Anlin Windows				
<div><div></div>Cabinet Connection</div>				
Code: ZZ_3211		Location:		
Category: Cabinets		Type:	Description: Scratches on drawer face in master bathroom	Incomplete
Partner: Cabinet Connection				
Code: ZZ_3216		Location:		
Category: Cabinets		Type:	Description: Drawer on left of sink in kitchen hard to open Scratches on door and drawer faces	Incomplete
Partner: Cabinet Connection				
Code: ZZ_3217		Location:		
Category: Cabinets		Type:	Description: Left side of oven Scratches on upper and lower cabinet faces	Incomplete
Partner: Cabinet Connection				
Code: ZZ_3218		Location:		
Category: Cabinets		Type:	Description: Right of oven Scratches on faces of cabinets uppers and lowers and on fridge surround	Incomplete
Partner: Cabinet Connection				
<div><div></div>De Young Properties</div>				
Code: ZZ_3223		Location:		
Category: Builder Personnel		Type:	Description: Scratches on tub in bath 2	Incomplete
Partner: De Young Properties				
Code: ZZ_3228		Location:		
Category: Builder Personnel		Type:	Description: Red glue on window frame in bed 3	Incomplete
Partner: De Young Properties				

All Defects

Lot 129/Tract 0273

Code: ZZ_3230

Category: Builder Personnel

Partner: De Young Properties

Location:

Type:

Description: Clean off back patio

Incomplete

 Donald P. Dick

Code: ZZ_3225

Category: HVAC

Partner: Donald P. Dick

Location:

Type:

Description: Exhaust fan cover not installed in bath 2

Incomplete

Code: ZZ_3231

Category: HVAC

Partner: Donald P. Dick

Location:

Type:

Description: Start up hvac

Incomplete

 Elia Painting

Code: ZZ_3207

Category: Paint

Partner: Elia Painting

Location:

Type:

Description: Paint touch up above shelf in master closet

Incomplete

Code: ZZ_3222

Category: Paint

Partner: Elia Painting

Location:

Type:

Description: Crack in corners of walls in bed 2 And paint touch up on wall by window

Incomplete

 Fenceworks

Code: ZZ_3232

Category: Fence


Partner: Fenceworks

Location:

Type:

Description: Fence missing

Incomplete

 Matthews Quality Construction

Code: ZZ_3220

Category: Millwork


Partner: Matthews Quality Construction




Location:

Type:

Description: Automatic close for garage door not installed

Incomplete

 Ohanians Drywall

Code: ZZ_3221	Location:		
Category: Drywall	Type:	Description: Drywall touch up in coat closet	Incomplete
Partner: Ohanians Drywall			
Code: ZZ_3226	Location:		
Category: Drywall	Type:	Description: Drywall touch up above mirror in bath 2	Incomplete
Partner: Ohanians Drywall			
Code: ZZ_3227	Location:		
Category: Drywall	Type:	Description: Small divot on wall in bed 3	Incomplete
Partner: Ohanians Drywall			
 Quality Plumbing			
Code: ZZ_3219	Location:		
Category: Plumbing	Type:	Description: Water heater not installed	Incomplete
Partner: Quality Plumbing			
 Tri Valley Plastering & Drywall			
Code: ZZ_3229	Location:		
Category: Stucco	Type:	Description: Stucco touch up front right of home	Incomplete
Partner: Tri Valley Plastering & Drywall			
 Visalia Tile			
Code: ZZ_3208	Location:		
Category: Tile	Type:	Description: Remove excess grout on tile in master shower	Incomplete
Partner: Visalia Tile			
Code: ZZ_3213	Location:		
Category: Tile	Type:	Description: Grout grout crack by slider Please clean excess grout off slider frame	Incomplete
Partner: Visalia Tile			

Code: ZZ_3214	Location:		
Category: Tile	Type:	Description: Scratches on tile in dining nook	Incomplete
Partner: Visalia Tile			
Code: ZZ_3215	Location:		
Category: Tile	Type:	Description: Fill grout bubbles in grout in dining nook	Incomplete
Partner: Visalia Tile			
<div>Westech</div>			
Code: ZZ_3209	Location:		
Category: Electrical	Type:	Description: Install outlet on left side of vanity in master bathroom	Incomplete
Partner: Westech			
Code: ZZ_3210	Location:		
Category: Electrical	Type:	Description: Vanity lights missing in master bathroom	Incomplete
Partner: Westech			
Code: ZZ_3224	Location:		
Category: Electrical	Type:	Description: Vanity light not installed in bath 2	Incomplete
Partner: Westech			