

Katy Church of Christ Benevolence Request Form

Check all that apply- Use separate sheet if needed

Name: Donna Sampay					
Age (optional): Un-known		Male		Female	
Family					
Current Address:		10801 Westpark Drive, # 2410, Houston, TX 77042			
Work Phone:				Home Phone:	
Cell Phone:		832-889-0806		Email Address:	
Spouse's Name (if applicable):					
Children's Names/Ages					
# of Family Members in Home?					
		Date		Date	
Request Made		08/06/2025		Response Call	
Request Approved		08/10/2025		Follow up Interview	
REQUESTED \$ 780.00		Food		Hotel	
Rent/Mortgage		Auto Repair ☒		Medicine	
Utility Bill		Auto Payment		Prayers	
				Gas	
				Medical Expenses	
				Budget Training	
PROVIDED: \$ 780.00		Food		Hotel	
Rent/Mortgage		Auto Repair ☒		Medicine	
Utility Bill		Auto Payment		Prayers	
				Gas	
				Medical Expenses	
				Budget Training	
Church of Christ Member?		Yes, Katy			
If Yes, A Member Where?					
If No, A Member Where?					
Does the family or individual want to study the Bible?				Yes	No
If yes, can someone from the Church contact them?				Yes	No
Has Family or individual had previous assistance?				Yes	No ☒
If Yes how much was given?		\$			
What was it for?					
Has family or individual received assistance from other churches/agencies				Yes ☒	No
If Yes how much was given?		\$			
What was it for?					
Does the family or individual want help budget planning?				Yes	No
If yes, can someone from the Church contact them?				Yes	No
Request Form Filled Out By:				Randy Anderson	
Approval made by:				Randy Anderson	
Comments:		The AC went out on Donna's car. She works as a mall cop at a strip mall, didn't have money to pay for the repair and asked the church for help. I paid \$780 to Tech boys of Katy to do the repair. The estimate and receipt are attached. Please take the funds from local benevolence budget 01-5000-101 and re-imburse Randy A for \$780.00 Thanks.			

TECH BOYS AUTOMOTIVE CENTER
27523 MORTON RD#2
KATY, TEXAS. 77493
Phone: 281-391-6633 Fax: 281-391-6399

INVOICE

6328

Org. Est. # 006356

INVOICE

Printed Date: 08/22/2025

Work Completed: 08/22/2025

Sampay, Donna

10801 Westpark Drive#2410

Houston, TX 77042

Office 832-889-0806

2020 Chevrolet - Spark LS - 1.4L, In-Line4 (85CI) VIN(A)

Lic # : SRZ3831

Odometer In : 48245

VIN # : KL8CB6SA7 LC424562

Part Description / Number	Qty	Sale	Ext	Labor Description	Ext
New a/c evaporator temperature sensor MF3423423	1.00	89.99	89.99	Replace sensor labor to replace a/c evaporator temp sensor	375.00
YF-1234 MFG432423	1.00	99.69	99.69	Service a/c Labor to service a/c, evacuate, recharge a/c system	187.50
Shop Supplies			3.79	Hazardous Materials	10.00

Org. Estimate 780.00 Revisions 0.00 Current Estimate 780.00

Labor:	562.50
Parts:	193.47
HazMat:	10.00
SubTotal:	765.97
Tax:	14.03
Total:	780.00
Bal Due:	\$780.00

[Payments -]

Vehicle Received: 8/22/2025

Customer Number : 1499

I hereby authorize the above repair work to be done along with the necessary material and hereby grant you and/or your employees permission to operate the car or truck herein described on street, highways or elsewhere for the purpose to testing and/or inspection. An express mechanic's lien is hereby acknowledged on above car or truck to secure the amount of repairs thereto. Warranty on parts and labor is two years or 24,000 miles whichever comes first. Warranty work has to be performed in our shop & cannot exceed the original cost of repair.

Signature _____ Date _____

Visit us on the web: www.TECHBOYSTEXAS.COM

Email Address: JOSE@SHELBYIMPORTS.COM

Radio (2 DTCs)

DTC	Description	Status
B1025:04	Left front audio output circuit open	DTC history status : History DTC current status : Current
B127B:2B	Rearview camera input signal circuit missing reference	DTC history status : History DTC current status : Not current

Technician Notes

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.

R-134

** YF 1234 system (3yrs)*

** parts * 89.99*

** Labor * 389.50*

** 500.00*

*Service ALC ? * 280.00*

** 780.00*

Disclaimer: This report provides a reference for vehicle inspection and maintenance only. Autel is not liable for any accident, property damage, or personal injury resulting from the use of this information.



Shop Name: Tech Boys Auto Service
Tel: 281-391-6633
Email:
Address: 27523 Morton Ranch Rd. #2

Report ID: MAXIA20250816095829
Test Time: 2025-08-16 09:58:29
Technician: --

2020 GM Vehicle Diagnostic Report

1/50-00

Vehicle Information

2020/GM/Chevrolet/
VIN: KL8CB6SA7LC424562

Odometer Reading: 46092.07miles
License Plate: --



Scan to download PDF

Customer Information

Name: --

Tel: --

Device Information

Scanner: MaxiCom Ultra Lite
Version: V18.10

Serial Number: V1DGPBC01355
Repair Order Number:
V1DGPBC0135520250816095526052

System Scanned (12)

System	Status/DTC
Engine control module	✓ 0
Transmission control module	✓ 0
Electronic brake control module	✓ 0
Inflatable restraint sensing and diagnostic module	✓ 0
Instrument cluster	✓ 0
Power steering control module	✓ 0
Body control module	✗ 1
Passenger presence module	✓ 0
Radio	✗ 2
Serial data gateway module - processor 1	✓ 0
Serial data gateway module - processor 2	✓ 0
Telematics communication interface control module	✓ 0

DTC (3)

Body control module (1 DTC)

DTC	Description	Status
B3933:00	Air conditioning evaporator temperature sensor circuit	DTC history status : History Since DTC clear : Failed Last test : Failed current DTC This ignition cycle : Failed MIL status : Not requested



www.autel.com

MaxiCom Ultra Lite