

ELI MOTORS LIMITED

49 VICTORIA ROAD, HENDON, LONDON, NW4 2RP
020 8203 6449, Sales 07950 250970
www.elimotors.co.uk



VEHICLE SERVICE HISTORY

Complete Maintenance Record

● 18 August 2025

INVOICE #89172

MILEAGE: 72,595 MI

Total: £70.02

RECORDED ENTRY

J O B D E S C R I P T I O N

- Carry Out Mot

● 28 August 2024

INVOICE #87525

MILEAGE: 65,859 MI

Total: £360.18

RECORDED ENTRY

J O B D E S C R I P T I O N

- Prepare Car For Mot
- Carry Out Diagnostic
- To Investigate Tyre Warning Light And Reset
- Fit Near Side Front Link
- Replace Offside Front Headlight Bulb And Adjust

P A R T S U S E D

%, Near Side Front Link

%, Offside Front Headlight Bulb

● 12 February 2024

INVOICE #86444

MILEAGE: 61,941 MI

Total: £1676.44

RECORDED ENTRY

J O B D E S C R I P T I O N

- Investigate Non-Start Carry Out Diagnostic
- Found Valvematic Unit Seized
- Get Access To Valvematic Unit
- Remove Engine And Rocker Cover
- Remove Valvematic Unit, Plus Supply And Fit New Unit
- Reassemble Per Removal
- Re-Calibrate Ecu System And Retest

ELI MOTORS LIMITED

49 VICTORIA ROAD, HENDON, LONDON, NW4 2RP
020 8203 6449, Sales 07950 250970
www.elimotors.co.uk



VEHICLE SERVICE HISTORY

Complete Maintenance Record

Page 2

● **13 July 2023** INVOICE #85721

MILEAGE: 57,446 MI

Total: £1100.54

RECORDED ENTRY

JOB DESCRIPTION

- Prepare Car For Mot And Supply And Fit Front Discs + Brake Pads And Replace N/S/ Rear Lamp And Fit O/S/Front Liner And Clips
- Carried Out A Small Service
- Replaced Engine Oil And Filter
- Topped Up All Under Bonnet Levels
- Checked External Lighting Operation
- Checked Front And Rear Brake Condition
- Adjusted Tyre Pressure's
- Carried Out Road Test (See Report For Any Defects Found)

PARTS USED

%, Front Discs + Brake Pads And Replace N/S/ Rear Lamp And Fit O/S/Front Liner And Clips
%, Engine Oil And Filter

TOTAL RECORDS

4

CUMULATIVE SPEND

£3207.18

Generated by Eli Motors Management Suite on Feb 11, 2026, 9:41:27 AM