

SAFETY INCIDENT & HAZARD REPORTS SUMMARY
Plant Operations & Maintenance Division

Report 1

Case ID: SIF-PDF-001
Job Role: Maintenance Worker
Department: Mechanical
Location: Unit A
Task: Scaffolding and Platform Assembly
Incident Type: Near Miss
Date/Time: 2026-09-02 08:30
Description: While working at 12m height, an unsecured scaffolding plank shifted. The worker caught the guardrail but was

Report 2

Case ID: SIF-PDF-002
Job Role: Senior Electrician
Department: Electrical
Location: Unit B
Task: 6.6kV Transformer Breaker Inspection
Incident Type: Unsafe Condition
Date/Time: 2026-09-02 11:00
Description: High voltage busbar inspection conducted without verifying zero electrical energy or applying lockout tagout pa

Report 3

Case ID: SIF-PDF-003
Job Role: Process Operator
Department: Operations
Location: Unit C
Task: Caustic Soda Unloading
Incident Type: Unsafe Act
Date/Time: 2026-09-02 14:15
Description: Operator disconnected chemical transfer hose before relieving line pressure, causing toxic caustic liquid splash