


# BuildScan Rover

## Modern Inspection Report

Generated: 22-04-2026 02:26 PM



**Size**  
258px

**Width**  
139px

**Confidence**  
93.83%

**Severity**  
MEDIUM

**Repair**  
Use epoxy injection repair

### AI Performance

Accuracy : 93.83%  
Precision : 92.83%  
Recall : 91.83%