

Inspection Report INS-2026009

Inspection Details

Report ID: INS-2026009
Equipment ID: P-102
Equipment: Centrifugal Pump
Inspection date: 2026-08-10
Vibration: 7.5 mm/s
Temperature: 73.2 °C
Observed status: CRITICAL
Recommendation: maintenance assessment.
This is a synthetic case for software testing.