

Inspection Report INS-2026004

Inspection Details

Report ID: INS-2026004
Equipment ID: P-104
Equipment: Centrifugal Pump
Inspection date: 2026-08-05
Vibration: 6.3 mm/s
Temperature: 78.8 °C
Observed status: WARNING
Recommendation: maintenance assessment.
This is a synthetic case for software testing.