

SteelSafe AI – Inspection Report

Date & Time: 2025-12-26 22:16:21.506374

Image Name: cast_def_0_333.jpeg

Inspection Result: Defect

Confidence: 99.6%

Status: Automatically generated by AI system