Savannah Tank & Equipment Corp.

RECEIVING INSPECTION REPORT

Job #: 089-25 PO# 40301 Date: 1/21/26 M&TE Serial # No serial number

Plate: **Quantity:** **Coded Marking:**

Spec. No.:	Grade:	Heat#:	
T-1:	T-2:	T-3:	T-4:
W:	L:	MTR Received: Yes No	
Other:			
Accepted:		Rejected:	



Heads & Caps: **Quantity:** **Coded Marking:**

Spec No.:	Grade:	Heat#:	
Stamping:			
O.D:	I.D.:	Depth:	L:
SL:	T-1:	T-2:	MTR Received: Yes No
Other:			
Accepted:		Rejected:	



Pipe: **Quantity:** **Coded Marking:**

Spec. No.:	Grade:	Heat#:	
I.D.:	O.D:	T-1:	T-2:
L:	MTR Received: Yes No		
Other:			
Accepted:		Rejected:	



Ells: **Quantity:** **Coded Marking:**

Spec. No.:	Grade:	Heat#:	
Other:		MTR Received: Yes No	
I.D.#1:	I.D.#2:	O.D.#1:	O.D.#2:
T-1:	T-2:	L-1:	L-2:
Stamping:			
Accepted:		Rejected:	



Other: 10" Flange **Quantity:** 2 **Coded Marking:**

Spec. No.: SA182	Grade: 2205	Heat: CH-181277	
Description: 10" ~~150#~~ ~~[illegible]~~ RF80 Flange			
Other:		MTR Received: Yes No	
List Inspection Points: L1: 2" T1: 1.177"		OD-P: 10.75" T2: 1.177"	OD-F: ~~[illegible]~~ 16"
Stamping: CHANDAN 10" SO RF 150 B16.5 FS1/60 SA/A182 CH-181277			
Accepted: AA		Rejected:	



Material Accepted: JR Date: 1/22/26

Line: 904