# Savannah Tank & Equipment Corp.

## RECEIVING INSPECTION REPORT

Job #: 08725 PO# 40304 Date: 1/21/26 M&TE Serial # No serial number

**Plate:** **Quantity:** **Coded Marking:**

| | | | |
|---|---|---|---|
| Spec. No.: | Grade: | Heat#: | |
| T-1: | T-2: | T-3: | T-4: |
| W: | L: | MTR Received: Yes No | |
| Other: | | | |
| Accepted: | | Rejected: | |




**Heads & Caps:** **Quantity:** **Coded Marking:**

| | | | |
|---|---|---|---|
| Spec No.: | Grade: | Heat#: | |
| Stamping: | | | |
| O.D: | I.D.: | Depth: | L: |
| SL: | T-1: | T-2: | MTR Received: Yes No |
| Other: | | | |
| Accepted: | | Rejected: | |




**Pipe:** **Quantity:** **Coded Marking:**

| | | | |
|---|---|---|---|
| Spec. No.: | Grade: | Heat#: | |
| I.D.: | O.D: | T-1: | T-2: |
| L: | MTR Received: Yes No | | |
| Other: | | | |
| Accepted: | | Rejected: | |




**Ells:** 3" Sch80 90° **Quantity:** 1 **Coded Marking:**

| | | | |
|---|---|---|---|
| Spec. No.: SA403 | Grade: 304/L | Heat#: 33x P321 | |
| Other: | | MTR Received: Yes No | |
| I.D.#1: 2.827" | I.D.#2: 2.827" | O.D.#1: 3.50" | O.D.#2: 3.50" |
| T-1: .340" | T-2: .333" | L-1: 3.50" | L-2: 3.50" |
| Stamping: MAC LR90 3" Sch80S A/SA403 WP304/304LS HT: 33X P321 MALAYSIA (2307) | | | |
| Accepted: AA | | Rejected: | |




**Other:** **Quantity:** **Coded Marking:**

| | | | |
|---|---|---|---|
| Spec. No.: | Grade: | Heat: | |
| Description: | | | |
| Other: | | MTR Received: Yes No | |
| List Inspection Points: L1: T1: | OD-P: T2: | OD-F: | |
| Stamping: | | | |
| Accepted: | | Rejected: | |




Material Accepted: JR Date: 1/22/26

Line: 006