LOGO	353 Amadeo Highway, Barangay Santiago, General Trias, Cavite, Philippines Tel. No.: (046) 683-7500 • (046) 683-7783 Telefax No.: (046) 432-5533	SY3-F-EPD-000 REV. 00 / 02-16-2025 PAGE 1 OF 2

ONSITE INSPECTION FORM

DATE INSPECTED:	2026-11-03	**OIF NO.:**	OIF-SAMPLE
PROJECT DESCRIPTION:	Pump overhaul sample	**RCE NO.:**	RCE-SAMPLE
CUSTOMER NAME:	Sample Client	**CUSTOMER REPRESENTATIVE:**	Engr. Sample
CLIENT ADDRESS:	General Trias, Cavite	**CONTACT NO.:**	09170000000

A. JOB TYPE

ACTIVITY: ☑ ONSITE ☑ SHOPWORK ☐ SUPPLY ONLY

SERVICE TYPE:

☑ REPAIR	☐ ELECTRICAL	☐ THERMAL SPRAY
☐ CIVIL WORKS	☐ NDT	☐ PROTECTIVE COATING
☐ FABRICATION	☐ BALANCING	☐ SANDBLASTING
☑ MECHANICAL	☑ OTHERS: *Laser alignment*	

CUSTOMER WORKING DRAWING AVAILABLE: ☑ YES ☐ NO

B. WORK PIECE MEASUREMENT

QUANTITY: 1

GENERAL DIMENSIONS (APPROXIMATELY)

LENGTH: 800	WIDTH: 400	**THK:**
OD:	**ID:**	**LENGTH:**

ESTIMATED WEIGHT

TONS: N/A	KG: N/A

DURATION: 5 days

C. SCOPE OF WORK

1 Dismantle

1.1 Tag parts

2 Overhaul

D. ESTIMATED MATERIALS

No.	Description	Qty	Unit
1	Gasket	2	pc

E. CONSUMABLES

No.	Description	Qty	Unit
1	Rags	1	kg

F. TOOLS AND EQUIPMENT

No.	Description	Qty	Unit
1	Dial indicator	1	set

G. ESTIMATED ACTIVITY DURATION WITH MANPOWER — 5 DAYS

NO.	DESIGNATION	NO. OF PERSONS	DAYS / HOURS	NO.	DESIGNATION	NO. OF PERSONS	DAYS / HOURS
1	Millwright	2	3 days				

ONSITE INSPECTION FORM

H. PHOTOS

I. REMARKS AND NOTES

REMARKS:
No obstruction.

NOTES:
1. Confirm isolation before work.

Prepared by:	Inspected by:	Reviewed by:
Test Estimator	Test Inspector	
Checked by:	**Noted by:**	**Approved by:**