

# Confirmed: RC1 reaches R18 via V053-V070

PIC12/RC1 -> V053 -> V070 -> R18.1. V053-VREF explicitly rejected; RB0/VREF stays separate.

Recorded from your continuity report; no numerical ohms supplied. This page now locates the completed connection. No repeat measurement requested. V067 also reaches J3 pin 1/red wire, on H\_PIR\_VDD.

| Test | Fixed probe | Moving probe | What this tests                  | Recorded result          |
|------|-------------|--------------|----------------------------------|--------------------------|
| F1   | V053        | V070         | PIC12/RC1 to R18.1 control input | Connected (user checked) |

What this resolves: RC1 supplies the R18 control input in the reconstructed circuit. The earlier photo-only RC1-to-VREF link was wrong and is withdrawn. RC2 now reaches TP3; RB0 reaches VREF (native TP104). All PIC pads have modeled local destinations; other circuit gaps remain.

A - V053: PIC pin 12 / RC1



B - V070: R18 control input



Evidence limits: V053-V070 is user-confirmed. The existing local V070-to-R18.1 pad association is retained. Q7/R19 base-emitter topology remains a photo/resistance-supported reconstruction, not a powered functional test.

Rear mosaic is already mirrored to match the front. Circles mark vias; leaders are annotations, not traces. Use board landmarks and the paired photo locator to zoom. The completed V064-V070 reading is resistive, not direct continuity.

No GPIO batch pending. Remaining work includes other hidden continuations, candidate identities, values and package geometry.