## A. DOCUMENT INFORMATION

| | |
|---|---|
| **Report ID** | MOTR-20261020-EE249E4FC3 |
| **Incident ID** | b0953b26-b868-4f2d-b0bf-49ad12ef0da8 |
| **Report Type** | MOTOR VEHICLE ACCIDENT INSURANCE CLAIM REPORT |
| **Generation Date/Time** | 2026-10-20T08:44:31Z |
| **Status** | Preliminary Documentation — Requires Verification |
| **Source** | Source: uploaded_video |

## B. INCIDENT OVERVIEW

| | |
|---|---|
| **Accident Date/Time** | 2026-10-20T08:43:23.316000+00:00 |
| **Accident Location** | Unknown |
| **GPS Coordinates** | Not available |
| **Maps Reference** | Not available |
| **Video Identifier** | https://res.cloudinary.com/ds9xucjmy/video/upload/v1792485738/nodh3wos95orceg |
| **Detection Model** | YOLOv8 AI Detection Pipeline |
| **Confidence Score** | Not available in supplied evidence |
| **Severity Estimate** | HIGH |

**Incident Description:**

The AI detection pipeline identified a high severity motor vehicle accident at 2026-10-20 08:43:23 UTC. The incident was captured in an uploaded video. No additional details regarding the vehicles or circumstances are available from the detection output.

## C. VEHICLE INFORMATION

| | |
|---|---|
| **Vehicle Owner** | Not available in supplied evidence — to be completed by claimant |
| **Registration Number** | Not available — number plate recognition not available in this system |
| **Vehicle Make / Model** | Not available in supplied evidence |
| **Insurance Company** | Not available in supplied evidence — to be completed by claimant |
| **Policy Number** | Not available in supplied evidence — to be completed by claimant |
| **Policy Validity** | Not available in supplied evidence — to be completed by claimant |
| **Claim Number** | To be assigned by insurer |

## D. OBSERVED ACCIDENT CIRCUMSTANCES

The AI system detected a high severity motor vehicle accident at the timestamp provided. No further details on the vehicles or collision dynamics are available.

**Important Note:** This description is based solely on automated video analysis. Fault determination, legal liability, and cause of accident require independent investigation by qualified authorities.

## E. VEHICLE DAMAGE OBSERVATIONS

| Vehicle / Component | Visible Observation | Evidence | Assessment Status |
|---|---|---|---|
| Overall Vehicle Condition | Not determinable from available footage — physical inspection required | Video evidence | Requires physical inspection by qualified asses |

Note: A physical inspection by a qualified assessor is required for an authoritative damage assessment. No repair costs, replacement values, or hidden damage should be assumed from this report alone.

## F. INCIDENT TIMELINE

| Event | Timestamp | Status | Evidence/Source |
|---|---|---|---|
| Accident Detected by AI System | 2026-10-20T08:43:23.316000+00:00 | Confirmed | AI Detection Pipeline |
| System Alert Generated | 2026-10-20T08:44:31Z | Completed | Application log |
| Emergency Services Response | Not recorded | Unknown — requires verification | Not available |

## G. EVIDENCE REGISTER

| Evidence Item | Reference | Status |
|---|---|---|
| Original Uploaded Video | https://res.cloudinary.com/ds9xucjmy/video/upload/v1792485738/no-accident-crash-9g | Available for review |
| Incident Record | ID: b0953b26-b868-4f2d-b0bf-49ad12ef0da8 | Stored in system database |
| Detection Metadata | Confidence: Not available, Severity: HIGH | Available |
| GPS/Location Data | Not available | Not available |

## H. MOTOR INSURANCE CLAIM CHECKLIST

| Document / Item | Status |
|---|---|
| Completed insurer claim form | To be completed by claimant |
| Valid motor insurance policy document | To be provided by claimant |
| Vehicle registration certificate (RC) | To be provided by claimant |
| Driving licence (valid at time of incident) | To be provided by claimant |
| Government-issued identity document | To be provided by claimant |
| Original accident video (from this system) | Available — reference above |
| Photographs of vehicle damage | To be captured at scene |
| Repair estimate from authorised workshop | To be obtained |
| Vehicle inspection/survey report | To be arranged with insurer |
| FIR or police report (where applicable) | To be obtained from local authority |
| Medical records and bills (if personal injury) | If applicable — to be provided |
| Additional documents as required by insurer | Verify with your insurance provider |

## I. DECLARATION AND LIMITATIONS

*DECLARATION AND LIMITATIONS: This document is an AI-assisted preliminary incident report generated by the SafeTrack AI accident detection system. It is NOT an official police report, independent accident surveyor's report, legal determination of liability, or guarantee of insurance claim approval. The information in this report is based solely on automated video analysis and must be verified by the claimant, insurance provider, and relevant authorities. Vehicle registration details, driver information, and damage assessments require physical verification. The user and insurer must independently verify all details before acting on this report. SafeTrack AI makes no representation regarding the accuracy of vehicle identification, incident cause, or liability.*

Claimant Signature: _____ Date: _____ Insurer Reference: _____