MOTOR INSURANCE CLAIM FORM

Private motor vehicle | Claim to be lodged within 30 days of the incident

POLICY NO. MIR-4471-8823-06

TYPE OF COVER Comprehensive

POLICY INCEPTION DATE 14/11/2025

POLICY EXPIRY DATE 14/11/2026

NAME OF INSURED

Tan Wei Ling

NRIC / FIN OF INSURED S7512048D

MOBILE NUMBER +65 9123 4488

ADDRESS OF INSURED

Blk 214 Tampines Street 21, #09-11, Singapore 520214

VEHICLE REGISTRATION NO. SLK4821J

MAKE Honda

MODEL City

YEAR OF MANUFACTURE 2019

CHASSIS / VIN NO. JHMHR2F50KE000341

ENGINE CAPACITY (CC) 1499

WAS THE VEHICLE DRIVEN BY THE INSURED? Yes

NAME OF DRIVER Tan Wei Ling

NRIC / FIN OF DRIVER S7512048D

PART B PARTICULARS OF THE INCIDENT

DATE OF ACCIDENT 12/03/2026

TIME OF ACCIDENT 08:41

PLACE OF ACCIDENT

Clementi Avenue 6, junction with Commonwealth Avenue West

NATURE OF LOSS / DAMAGE

- [x] Collision
- [ ] Theft
- [ ] Fire
- [ ] Flood
- [ ] Wind & Hail
- [ ] Glass Damage
- [ ] Third Party Property Damage
- [ ] Found Damaged

STATE FULLY WHAT HAPPENED

I was stopped at the red light at the junction of Clementi Avenue 6 and Commonwealth Avenue West when a lorry reversed into the rear of my car. The driver stopped and admitted fault. The rear bumper and boot lid are dented and scratched. There was no visible glass breakage. I called the police and an officer attended.

POLICE REPORT REFERENCE CASE 26/0312/0417

POLICE STATION / DIVISION Clementi Police Division

WERE ANY PERSONS INJURED? No

WAS A THIRD PARTY INVOLVED? Yes

THIRD PARTY NAME

Sembcorp Logistics Pte Ltd (driver: Mr Lim Boon Heng)

THIRD PARTY VEHICLE REG. NO. YH9127B

WITNESSES (NAME & CONTACT)

Mr Tan Ah Kow, +65 9432 1188 (waiting at the light)

PART C DETAILS OF DAMAGE

DAMAGED PARTS

- [ ] Front Bumper
- [x] Rear Bumper
- [ ] Front Bonnet
- [x] Boot Lid
- [ ] Front Left Wing
- [ ] Front Right Wing
- [ ] Rear Left Wing
- [ ] Rear Right Wing
- [ ] Front Left Door
- [ ] Front Right Door
- [ ] Rear Left Door
- [ ] Rear Right Door
- [ ] Roof Panel
- [ ] Left Side Mirror
- [ ] Right Side Mirror
- [ ] Front Left Headlamp
- [ ] Front Right Headlamp
- [ ] Rear Left Tail Lamp
- [ ] Rear Right Tail Lamp
- [ ] Windscreen
- [ ] Rear Window
- [ ] Side Window (front left)
- [ ] Side Window (front right)
- [ ] Front Left Tyre
- [ ] Front Right Tyre
- [ ] Rear Left Tyre
- [ ] Rear Right Tyre

EXTENT OF DAMAGE

- [ ] Minor cosmetic
- [x] Moderate
- [ ] Severe
- [ ] Vehicle not drivable

IS THE VEHICLE STILL ROADWORTHY?	Yes
NO. OF PHOTOGRAPHS ATTACHED	2
ESTIMATED LOSS (SGD)	$ 6,317.64
REPAIRER / WORKSHOP	AutoCare Works Pte Ltd
REPAIR QUOTATION REFERENCE	Q-2026-0312-ACW

PART D DECLARATION

DECLARATION

I declare that the information given on this form is true and correct, that the loss described above has occurred, and that I am entitled to claim under the policy identified above. I understand that a false declaration may prejudice my claim and may constitute an offence.

DATE OF SIGNING	13/03/2026
DECLARATION ACCEPTED	Yes

FOR OFFICE USE ONLY - leave blank. Assessor reference, risk band, and approval signature recorded in the claims system.