MOTOR INSURANCE CLAIM FORM

Private motor vehicle | Claim to be lodged within 30 days of the incident

POLICY NO. MIR-6644-2287-01

TYPE OF COVER Comprehensive

POLICY INCEPTION DATE 25/06/2026

POLICY EXPIRY DATE 25/06/2027

NAME OF INSURED

Aisha binti Osman

NRIC / FIN OF INSURED S9412290R

MOBILE NUMBER +65 9655 3308

ADDRESS OF INSURED

65 Yio Chu Kang Road,
#04-09, Singapore 787605

VEHICLE REGISTRATION NO. PMN6118D

MAKE Mitsubishi

MODEL Lancer

YEAR OF MANUFACTURE 2015

CHASSIS / VIN NO. J3A3SC1CJ5E044771

ENGINE CAPACITY (CC) 1598

WAS THE VEHICLE DRIVEN BY THE INSURED? Yes

NAME OF DRIVER Aisha binti Osman

NRIC / FIN OF DRIVER S9412290R

PART B PARTICULARS OF THE INCIDENT

DATE OF ACCIDENT 03/07/2026

TIME OF ACCIDENT 10:15

PLACE OF ACCIDENT

Yio Chu Kang Road,
Hougang Car Park B

NATURE OF LOSS / DAMAGE

- [x] Collision
- [ ] Theft
- [ ] Fire
- [ ] Flood
- [ ] Wind & Hail
- [ ] Glass Damage
- [ ] Third Party Property Damage
- [ ] Found Damaged

STATE FULLY WHAT HAPPENED

A lorry reversed into me at speed in the car park and pushed my car into a concrete pillar. The rear of the vehicle is crushed and badly deformed. The rear left wing and rear bumper are wrecked. There was a loud bang and I was shaken. The impact was very heavy.

POLICE REPORT REFERENCE CASE 26/0703/0219

POLICE STATION / DIVISION Hougang Police Division

WERE ANY PERSONS INJURED? No

WAS A THIRD PARTY INVOLVED? Yes

THIRD PARTY NAME Lorry company, per police report

THIRD PARTY VEHICLE REG. NO. Per police report

WITNESSES (NAME & CONTACT) —

PART C DETAILS OF DAMAGE

DAMAGED PARTS

- [ ] Front Bumper
- [x] Rear Bumper
- [ ] Front Bonnet
- [ ] Boot Lid
- [ ] Front Left Wing
- [ ] Front Right Wing
- [x] Rear Left Wing
- [ ] Rear Right Wing
- [ ] Front Left Door
- [ ] Front Right Door
- [ ] Rear Left Door
- [ ] Rear Right Door
- [ ] Roof Panel
- [ ] Left Side Mirror
- [ ] Right Side Mirror
- [ ] Front Left Headlamp
- [ ] Front Right Headlamp
- [ ] Rear Left Tail Lamp
- [ ] Rear Right Tail Lamp
- [ ] Windscreen
- [ ] Rear Window
- [ ] Side Window (front left)
- [ ] Side Window (front right)
- [ ] Front Left Tyre
- [ ] Front Right Tyre
- [ ] Rear Left Tyre
- [ ] Rear Right Tyre

EXTENT OF DAMAGE

- [ ] Minor cosmetic
- [x] Moderate
- [ ] Severe
- [ ] Vehicle not drivable

IS THE VEHICLE STILL ROADWORTHY?
Yes

NO. OF PHOTOGRAPHS ATTACHED
2

ESTIMATED LOSS (SGD)
$ 2,144.14

REPAIRER / WORKSHOP
Hougang Auto Pte Ltd

REPAIR QUOTATION REFERENCE
Q-2026-0703-HAA

PART D DECLARATION

DECLARATION

I declare that the information given on this form is true and correct, that the loss described above has occurred, and that I am entitled to claim under the policy identified above. I understand that a false declaration may prejudice my claim and may constitute an offence.

DATE OF SIGNING
04/07/2026

DECLARATION ACCEPTED
Yes

FOR OFFICE USE ONLY - leave blank. Assessor reference, risk band, and approval signature recorded in the claims system.