# MOTOR INSURANCE CLAIM FORM

Private motor vehicle | Claim to be lodged within 30 days of the incident

**POLICY NO.** MIR-3362-8890-04

**TYPE OF COVER** Comprehensive

**POLICY INCEPTION DATE** 10/04/2026

**POLICY EXPIRY DATE** 10/04/2027

**NAME OF INSURED** Rajesh s/o Muthu

**NRIC / FIN OF INSURED** S9211078N

**MOBILE NUMBER** +65 9811 4472

**ADDRESS OF INSURED** 640 Ang Mo Kio Avenue 10, #07-14, Singapore 560640

**VEHICLE REGISTRATION NO.** JFD7741R

**MAKE** Kia

**MODEL** Cerato

**YEAR OF MANUFACTURE** 2020

**CHASSIS / VIN NO.** KNAP4A19A8T602255

**ENGINE CAPACITY (CC)** 1598

**WAS THE VEHICLE DRIVEN BY THE INSURED?** Yes

**NAME OF DRIVER** Rajesh s/o Muthu

**NRIC / FIN OF DRIVER** S9211078N

## PART B PARTICULARS OF THE INCIDENT

**DATE OF ACCIDENT** 24/07/2026

**TIME OF ACCIDENT** 13:30

**PLACE OF ACCIDENT** Bedok North Street 1, outside Blk 660

**NATURE OF LOSS / DAMAGE**

- [x] Collision
- [ ] Theft
- [ ] Fire
- [ ] Flood
- [ ] Wind & Hail
- [ ] Glass Damage
- [ ] Third Party Property Damage
- [ ] Found Damaged

**STATE FULLY WHAT HAPPENED**

I was reversing out of my parking bay when a delivery lorry came through at speed and hit the car. The front bumper and rear bumper are both smashed and the front left headlamp is broken. The lorry hit the front and then the back as it swung across. The windscreen is cracked. The driver did not stop.

**POLICE REPORT REFERENCE** Not required / not taken

**POLICE STATION / DIVISION** —

**WERE ANY PERSONS INJURED?** No

**WAS A THIRD PARTY INVOLVED?** Yes

**THIRD PARTY NAME** Not recorded

**THIRD PARTY VEHICLE REG. NO.** Not recorded

**WITNESSES (NAME & CONTACT)** —

## PART C DETAILS OF DAMAGE

**DAMAGED PARTS**

- [x] Front Bumper
- [x] Rear Bumper
- [ ] Front Bonnet
- [ ] Boot Lid
- [ ] Front Left Wing
- [ ] Front Right Wing
- [ ] Rear Left Wing
- [ ] Rear Right Wing
- [ ] Front Left Door
- [ ] Front Right Door
- [ ] Rear Left Door
- [ ] Rear Right Door
- [ ] Roof Panel
- [ ] Left Side Mirror
- [ ] Right Side Mirror
- [x] Front Left Headlamp
- [ ] Front Right Headlamp
- [ ] Rear Left Tail Lamp
- [ ] Rear Right Tail Lamp
- [x] Windscreen
- [ ] Rear Window
- [ ] Side Window (front left)
- [ ] Side Window (front right)
- [ ] Front Left Tyre
- [ ] Front Right Tyre
- [ ] Rear Left Tyre
- [ ] Rear Right Tyre

**EXTENT OF DAMAGE**

- [ ] Minor cosmetic
- [x] Moderate
- [ ] Severe
- [ ] Vehicle not drivable

**IS THE VEHICLE STILL ROADWORTHY?**
Yes

**NO. OF PHOTOGRAPHS ATTACHED**
2

**ESTIMATED LOSS (SGD)**
$ 10,707.12

**REPAIRER / WORKSHOP**
Bedok Motorworks Pte Ltd

**REPAIR QUOTATION REFERENCE**
Q-2026-0724-BMW

## PART D DECLARATION

**DECLARATION**

I declare that the information given on this form is true and correct, that the loss described above has occurred, and that I am entitled to claim under the policy identified above. I understand that a false declaration may prejudice my claim and may constitute an offence.

**DATE OF SIGNING**
24/07/2026

**DECLARATION ACCEPTED**
Yes

FOR OFFICE USE ONLY - leave blank. Assessor reference, risk band, and approval signature recorded in the claims system.