MOTOR INSURANCE CLAIM FORM

Private motor vehicle | Claim to be lodged within 30 days of the incident

POLICY NO. MIR-8817-2205-08

TYPE OF COVER Comprehensive

POLICY INCEPTION DATE 15/02/2026

POLICY EXPIRY DATE 15/02/2027

NAME OF INSURED

Ong Chee Keong

NRIC / FIN OF INSURED S7907114X

MOBILE NUMBER +65 8123 9908

ADDRESS OF INSURED

11 Sinaran Mirage,
#16-04, Singapore 307100

VEHICLE REGISTRATION NO. KDM9035T

MAKE Subaru

MODEL Impreza

YEAR OF MANUFACTURE 2018

CHASSIS / VIN NO. JF1RR2F80FH044118

ENGINE CAPACITY (CC) 1995

WAS THE VEHICLE DRIVEN BY THE INSURED? Yes

NAME OF DRIVER Ong Chee Keong

NRIC / FIN OF DRIVER S7907114X

PART B PARTICULARS OF THE INCIDENT

DATE OF ACCIDENT 11/08/2026

TIME OF ACCIDENT 21:02

PLACE OF ACCIDENT

Sinaran Drive service
road, near thePIB junction

NATURE OF LOSS / DAMAGE

- [x] Collision
- [ ] Theft
- [ ] Fire
- [ ] Flood
- [ ] Wind & Hail
- [ ] Glass Damage
- [ ] Third Party Property Damage
- [ ] Found Damaged

STATE FULLY WHAT HAPPENED

I was hit from behind by a van at high speed on the Sinaran Drive service road. The whole rear of the car is destroyed. The vehicle is not drivable and I have had to write it off. The rear left door and boot lid are completely destroyed.

POLICE REPORT REFERENCE CASE 26/0811/0755

POLICE STATION / DIVISION Serangoon Police Division

WERE ANY PERSONS INJURED? No

WAS A THIRD PARTY INVOLVED? Yes

THIRD PARTY NAME

Van driver, details
recorded by police

THIRD PARTY VEHICLE REG. NO. GEF8814S

WITNESSES (NAME & CONTACT) —

PART C DETAILS OF DAMAGE

DAMAGED PARTS

- [ ] Front Bumper
- [ ] Rear Bumper
- [ ] Front Bonnet
- [x] Boot Lid
- [ ] Front Left Wing
- [ ] Front Right Wing
- [ ] Rear Left Wing
- [ ] Rear Right Wing
- [ ] Front Left Door
- [ ] Front Right Door
- [x] Rear Left Door
- [ ] Rear Right Door
- [ ] Roof Panel
- [ ] Left Side Mirror
- [ ] Right Side Mirror
- [ ] Front Left Headlamp
- [ ] Front Right Headlamp
- [ ] Rear Left Tail Lamp
- [ ] Rear Right Tail Lamp
- [ ] Windscreen
- [ ] Rear Window
- [ ] Side Window (front left)
- [ ] Side Window (front right)
- [ ] Front Left Tyre
- [ ] Front Right Tyre
- [ ] Rear Left Tyre
- [ ] Rear Right Tyre

EXTENT OF DAMAGE

- [ ] Minor cosmetic
- [ ] Moderate
- [ ] Severe
- [x] Vehicle not drivable

IS THE VEHICLE STILL ROADWORTHY? No

NO. OF PHOTOGRAPHS ATTACHED 2

ESTIMATED LOSS (SGD) $ 14,800.00

REPAIRER / WORKSHOP AutoCare Works Pte Ltd

REPAIR QUOTATION REFERENCE Q-2026-0811-ACW

PART D DECLARATION

DECLARATION

I declare that the information given on this form is true and correct, that the loss described above has occurred, and that I am entitled to claim under the policy identified above. I understand that a false declaration may prejudice my claim and may constitute an offence.

DATE OF SIGNING 11/08/2026

DECLARATION ACCEPTED Yes

FOR OFFICE USE ONLY - leave blank. Assessor reference, risk band, and approval signature recorded in the claims system.