MOTOR INSURANCE CLAIM FORM

Private motor vehicle | Claim to be lodged within 30 days of the incident

POLICY NO. MIR-8113-6648-10

TYPE OF COVER Third Party + Fire & Theft

POLICY INCEPTION DATE 01/12/2025

POLICY EXPIRY DATE 01/12/2026

NAME OF INSURED Priya d/o Selvam

NRIC / FIN OF INSURED S9421033Y

MOBILE NUMBER +65 9988 1177

ADDRESS OF INSURED 175 Bencoolen Street, #11-09, Singapore 189648

VEHICLE REGISTRATION NO. DGF2755K

MAKE Renault

MODEL Koleos

YEAR OF MANUFACTURE 2019

CHASSIS / VIN NO. VF1KDD7G635012204

ENGINE CAPACITY (CC) 1997

WAS THE VEHICLE DRIVEN BY THE INSURED? Yes

NAME OF DRIVER Priya d/o Selvam

NRIC / FIN OF DRIVER S9421033Y

PART B PARTICULARS OF THE INCIDENT

DATE OF ACCIDENT 01/09/2026

TIME OF ACCIDENT 12:05

PLACE OF ACCIDENT Bishan Junction 8, level 1 car park

NATURE OF LOSS / DAMAGE

- [x] Collision
- [ ] Theft
- [ ] Fire
- [ ] Flood
- [ ] Wind & Hail
- [ ] Glass Damage
- [ ] Third Party Property Damage
- [ ] Found Damaged

STATE FULLY WHAT HAPPENED

My car was involved in a collision on the way home. I was parking at Bishan Junction 8 and another car reversed into me. The front and rear bumpers and both front wings are all scratched. I am claiming against the other vehicle which I believe is uninsured. It was a fairly serious incident.

POLICE REPORT REFERENCE Not required / not taken

POLICE STATION / DIVISION —

WERE ANY PERSONS INJURED? No

WAS A THIRD PARTY INVOLVED? Yes

THIRD PARTY NAME Unknown - vehicle did not stop

THIRD PARTY VEHICLE REG. NO. Unknown

WITNESSES (NAME & CONTACT) —

PART C DETAILS OF DAMAGE

DAMAGED PARTS

- [x] Front Bumper
- [x] Rear Bumper
- [ ] Front Bonnet
- [ ] Boot Lid
- [x] Front Left Wing
- [x] Front Right Wing
- [ ] Rear Left Wing
- [ ] Rear Right Wing
- [ ] Front Left Door
- [ ] Front Right Door
- [ ] Rear Left Door
- [ ] Rear Right Door
- [ ] Roof Panel
- [ ] Left Side Mirror
- [ ] Right Side Mirror
- [ ] Front Left Headlamp
- [ ] Front Right Headlamp
- [ ] Rear Left Tail Lamp
- [ ] Rear Right Tail Lamp
- [ ] Windscreen
- [ ] Rear Window
- [ ] Side Window (front left)
- [ ] Side Window (front right)
- [ ] Front Left Tyre
- [ ] Front Right Tyre
- [ ] Rear Left Tyre
- [ ] Rear Right Tyre

EXTENT OF DAMAGE

- [x] Minor cosmetic
- [ ] Moderate
- [ ] Severe
- [ ] Vehicle not drivable

IS THE VEHICLE STILL ROADWORTHY?
Yes

NO. OF PHOTOGRAPHS ATTACHED
3

ESTIMATED LOSS (SGD)
$ 4,147.22

REPAIRER / WORKSHOP
Premium Auto Gallery Pte Ltd

REPAIR QUOTATION REFERENCE
Q-2026-0901-PAG

PART D DECLARATION

DECLARATION

I declare that the information given on this form is true and correct, that the loss described above has occurred, and that I am entitled to claim under the policy identified above. I understand that a false declaration may prejudice my claim and may constitute an offence.

DATE OF SIGNING
01/09/2026

DECLARATION ACCEPTED
Yes

FOR OFFICE USE ONLY - leave blank. Assessor reference, risk band, and approval signature recorded in the claims system.