MOTOR INSURANCE CLAIM FORM

Private motor vehicle | Claim to be lodged within 30 days of the incident

POLICY NO. MIR-1908-7734-06

TYPE OF COVER Comprehensive

POLICY INCEPTION DATE 05/05/2026

POLICY EXPIRY DATE 05/05/2027

NAME OF INSURED Ng Yi Xuan

NRIC / FIN OF INSURED S0511021E

MOBILE NUMBER +65 9100 2256

ADDRESS OF INSURED 48 Commonwealth Drive, #10-13, Singapore 140048

VEHICLE REGISTRATION NO. RYT4380E

MAKE Volkswagen

MODEL Golf

YEAR OF MANUFACTURE 2021

CHASSIS / VIN NO. WVWZZZ1KZAW000712

ENGINE CAPACITY (CC) 1395

WAS THE VEHICLE DRIVEN BY THE INSURED? Yes

NAME OF DRIVER Ng Yi Xuan

NRIC / FIN OF DRIVER S0511021E

PART B PARTICULARS OF THE INCIDENT

DATE OF ACCIDENT 26/08/2026

TIME OF ACCIDENT 07:55

PLACE OF ACCIDENT Commonwealth Avenue West, near Clementi MRT

NATURE OF LOSS / DAMAGE

- [x] Collision
- [ ] Theft
- [ ] Fire
- [ ] Flood
- [ ] Wind & Hail
- [ ] Glass Damage
- [ ] Third Party Property Damage
- [ ] Found Damaged

STATE FULLY WHAT HAPPENED

A cyclist came off their bicycle into the front left of my car on Commonwealth Avenue West. The wing took a solid knock and is dented. I have photographs taken at the scene and the car drives normally.

POLICE REPORT REFERENCE Not required / not taken

POLICE STATION / DIVISION —

WERE ANY PERSONS INJURED? Yes

WAS A THIRD PARTY INVOLVED? Yes

THIRD PARTY NAME Cyclist - Mr Daniel Wong, hospitalised

THIRD PARTY VEHICLE REG. NO. Not applicable

WITNESSES (NAME & CONTACT) Passerby helped the cyclist, name not recorded

PART C DETAILS OF DAMAGE

DAMAGED PARTS

- [ ] Front Bumper
- [ ] Rear Bumper
- [ ] Front Bonnet
- [ ] Boot Lid
- [x] Front Left Wing
- [ ] Front Right Wing
- [ ] Rear Left Wing
- [ ] Rear Right Wing
- [ ] Front Left Door
- [ ] Front Right Door
- [ ] Rear Left Door
- [ ] Rear Right Door
- [ ] Roof Panel
- [ ] Left Side Mirror
- [ ] Right Side Mirror
- [ ] Front Left Headlamp
- [ ] Front Right Headlamp
- [ ] Rear Left Tail Lamp
- [ ] Rear Right Tail Lamp
- [ ] Windscreen
- [ ] Rear Window
- [ ] Side Window (front left)
- [ ] Side Window (front right)
- [ ] Front Left Tyre
- [ ] Front Right Tyre
- [ ] Rear Left Tyre
- [ ] Rear Right Tyre

EXTENT OF DAMAGE

- [ ] Minor cosmetic
- [x] Moderate
- [ ] Severe
- [ ] Vehicle not drivable

IS THE VEHICLE STILL ROADWORTHY?
Yes

NO. OF PHOTOGRAPHS ATTACHED
1

ESTIMATED LOSS (SGD)
$ 3,955.07

REPAIRER / WORKSHOP
Premium Auto Gallery Pte Ltd

REPAIR QUOTATION REFERENCE
Q-2026-0826-PAG

PART D DECLARATION

DECLARATION

I declare that the information given on this form is true and correct, that the loss described above has occurred, and that I am entitled to claim under the policy identified above. I understand that a false declaration may prejudice my claim and may constitute an offence.

DATE OF SIGNING
26/08/2026

DECLARATION ACCEPTED
Yes

_____ _____

FOR OFFICE USE ONLY - leave blank. Assessor reference, risk band, and approval signature recorded in the claims system.