
October 7, 2022

To: Owen Walbert, Terry Watts, Bobby Williams, Angel Cruz, Alex Granados, Jesus Zelaya, Ryan Beery

From: Jesus Zelaya

This report is a follow up to the safety inspection completed on October 7, 2022. the purpose of the inspection was to identify potential safety hazards and/or OSHA violations.

Attached is a list of observations and recommendations based on the conditions present at the time of my visit. Please review the report and verify that all potential hazards are corrected.

If you have any questions or require additional information after reviewing this report, please don't hesitate to contact me.

Sincerely,

Jesus Zelaya
LF Jennings, Inc.
Safety Department
(703) 336-2023
jesus.zelaya@lfjennings.net

10/17/2022

Project Safety Inspection

Art Place Safety Report

Reported by: Jesus Zelaya

On-site Supervisor: Terry Watts

Scope of inspection: Here are the item we spotted today 10/07/22 in
the safety inspection

Observation 1

Precautions

On the North side the Guardrails needs flagging.



Observation 2

Access

We have 3 good access to the excavation and ladder is 3 feet above landing area



Observation 3

Precautions

Here we found the crane today was not in operations but still have orange cone around .



Observation 4

Storage

West Side area we found a oxygen cilynder on the floor . Needs to be in a case and protected from impact



Observation 5

Fall hazard


Here is the correction from a item we found in our last inspection
10/03/22 the guardrail now is proper installed.



Observation 6

Fire protection

Here we have diesel tank and there is not fire extinguishers.
Miller&longs needs fire extinguishers in there area



Observation 7

Storage

Here we found Oxygen Cylinders storage and secured properly





Submitted by:
Jesus Zelaya

L.F. Jennings.
Safety Department
(703) 336-2023
jesus.zelaya@lfjennings.net