

Maintenance System

1. Sidebar Data Form Permintaan Perbaikan

The screenshot shows the 'List Data Form FPP' table in the Maintenance System. The table has 10 columns: No, Nomor FPP, Mesin, Section, Lokasi, Kendala, Status, Created Date, Last Update, and Actions. The data is as follows:

No	Nomor FPP	Mesin	Section	Lokasi	Kendala	Status	Created Date	Last Update	Actions
1	FP0105	CC3	Bubut	D58	Salah Sparepart	ON PROGRESS	2024-02-16 08:29:47	2024-03-18 08:46:44	
2	FP0114	CC3	Machining	D58	Salah Sparepart	CLOSED	2024-03-18 08:09:08	2024-03-18 08:10:07	
3	FP0113	CC3	MC Custom	D58	Sparepart Rusak	CLOSED	2024-03-13 13:49:27	2024-03-13 13:53:56	
4	FP0108	CC1	Bubut	D58	d	CLOSED	2024-03-01 09:40:35	2024-03-06 13:18:22	
5	FP0112	CC3	MC Custom	D58	Salah Sparepart	CLOSED	2024-03-06 13:07:01	2024-03-06 13:18:10	
6	FP0111	CC4	Bubut	D58	Salah Sparepart	OPEN	2024-03-06 11:21:43	2024-03-06 11:21:43	
7	FP0110	CC2	MC Custom	Deltamas	Salah Isi	CLOSED	2024-03-04 17:34:26	2024-03-05 07:55:15	
8	FP0109	CC2	Cutting	D58	Oke	CLOSED	2024-03-04 16:11:45	2024-03-04 16:12:14	
9	FP0107	CC3	Machining	D58	Sparepart	CLOSED	2024-02-26 08:42:17	2024-02-26 08:55:54	
10	FP0106	CC2	MC Custom	D58	Wolkeh Siapp	FINISH	2024-02-16 08:37:24	2024-02-16 19:03:47	

2. Action Lihat : Riwayat Proses Perbaikan

The screenshot shows the 'FPP View Form' and 'History Progress Table' in the Maintenance System. The 'FPP View Form' has the following fields:

- Applicant*: Rina Suryani
- Date*: 03-Feb-2024
- Section*: Lathe
- Machine*: CC3
- Machine Location*: D58
- Constraints*: Salah Sparepart
- Picture: Image Preview

The 'History Progress Table' has 10 columns: No, Follow-up, Checking Schedule, Operator, Due Date, File, Status, Note, and Last Update. The data is as follows:

No	Follow-up	Checking Schedule	Operator	Due Date	File	Status	Note	Last Update
1			PIC		N/A	OVEN	FPP FORM CREATED	2024-02-16 08:29:47
2			PIC		N/A	ON PROGRESS	BEING FOLLOWED UP	2024-02-16 08:30:05
3			PIC		N/A	ON PROGRESS	BEING FOLLOWED UP	2024-02-16 08:30:05
4			PIC		gunung.jpg	ON PROGRESS	BEING FOLLOWED UP	2024-02-16 08:32:48
5		2024-02-16	PIC	2024-02-15	N/A	ON PROGRESS	BEING FOLLOWED UP	2024-02-26 09:20:32
6		2024-02-17	PIC	2024-02-15	N/A	ON PROGRESS	BEING FOLLOWED UP	2024-02-26 09:22:03
7		2024-02-15	PIC	2024-02-15	gunung.jpg	ON PROGRESS	BEING FOLLOWED UP	2024-02-26 11:18:05
8	Wrong Contents	2024-02-15	PIC	2024-02-15	Microsoft Certification.pdf	ON PROGRESS	BEING FOLLOWED UP	2024-03-05 08:04:00
9	Wrong Contents	2024-02-15	PIC	2024-02-15	N/A	ON PROGRESS	BEING FOLLOWED UP	2024-03-12 09:11:43

3. Create Form Permintaan Perbaikan

Form Create FPP

Pemohon*

Date*

dd-----yyyy

Pilih Section*

Select Section

Pilih Mesin*

Select Mesin

Lokasi Mesin*

Select Lokasi Mesin

Kendala*

Upload Gambar (Jika Ada)

Choose File No file chosen

Submit Reset

4. Sidebar maintenance terima Form Permintaan Perbaikan


Data Tables

List Data Received FPP

No	Mesin	Section	Lokasi	Kendala	Status	Created Date	Last Update	Actions
1	CC3	Bubut	D58	Salah Sparepart	ON PROGRESS	2024-02-16 08:29:47	2024-03-18 08:46:44	
2	CC3	Machining	D58	Salah Sparepart	CLOSED	2024-03-18 08:09:08	2024-03-18 08:10:07	
3	CC3	MC Custom	D58	Sparepart Rusak	CLOSED	2024-03-13 13:49:27	2024-03-13 13:53:56	
4	CC1	Bubut	D58	d	CLOSED	2024-03-01 09:40:35	2024-03-06 13:18:22	
5	CC3	MC Custom	D58	Salah Sparepart	CLOSED	2024-03-06 13:07:01	2024-03-06 13:18:10	
6	CC4	Bubut	D58	Salah Sparepart	OPEN	2024-03-06 11:21:43	2024-03-06 11:21:43	
7	CC2	MC Custom	Detamas	Salah Isi	CLOSED	2024-03-04 17:34:26	2024-03-05 07:55:15	
8	CC2	Cutting	D58	Oke	CLOSED	2024-03-04 16:11:45	2024-03-04 16:12:14	
9	CC3	Machining	D58	Sparepart	CLOSED	2024-02-26 08:42:17	2024-02-26 08:55:54	
10	CC2	MC Custom	D58	Wokeh Siapp	FINISH	2024-02-16 08:37:24	2024-02-16 19:03:47	

Showing 1 to 10 of 27 entries

5. Action Lihat



Card Form Lihat FPP

Form Lihat FPP

Mesin*

CC3

Section*

Bubut

Lokasi Mesin*

DS8

Kendala*

Salah Sparepart

Gambar

 Preview Gambar

Card Update Progress

Update Progress

Tindak Lanjut

Salah Isi

Due Date

15-Feb-2024

Schedule Pengecekan

15-Feb-2024

Attachment File

[assets/attachment/Muka_Aku.jpg](#)

Card Tabel History Progress

10 entries per page

No	Tindak Lanjut	Schedule Pengecekan	Operator	Due Date	File	Status	Note	Last Update
1			PIC		N/A	OPEN	FORM FPP DIBUAT	2024-02-16 08:29:47
2			PIC		N/A	ON PROGRESS	SEDANG DITINDAKLANJUTI	2024-02-16 08:30:05
3			PIC		N/A	ON PROGRESS	SEDANG DITINDAKLANJUTI	2024-02-16 08:30:05
4			PIC		gunung.jpg	ON PROGRESS	SEDANG DITINDAKLANJUTI	2024-02-16 08:32:48
5		2024-02-16	PIC	2024-02-15	N/A	ON PROGRESS	SEDANG DITINDAKLANJUTI	2024-02-26 09:20:32
6		2024-02-17	PIC	2024-02-15	N/A	ON PROGRESS	SEDANG DITINDAKLANJUTI	2024-02-26 09:22:03
7		2024-02-15	PIC	2024-02-15	gunung.jpg	ON PROGRESS	SEDANG DITINDAKLANJUTI	2024-02-26 11:18:05
8	Salah Isi	2024-02-15	PIC	2024-02-15	Microsoft Certification.pdf	ON PROGRESS	SEDANG DITINDAKLANJUTI	2024-03-05 08:04:00
9	Salah Isi	2024-02-15	PIC	2024-02-15	N/A	ON PROGRESS	SEDANG DITINDAKLANJUTI	2024-03-12 09:11:43
10	Salah Isi	2024-02-15	PIC	2024-02-15	adasi-icon.png	ON PROGRESS	SEDANG DITINDAKLANJUTI	2024-03-12 09:43:55

Showing 1 to 10 of 16 entries

6. Sidebar Dephead Maintenance

10 entries per page

No	Nomor FPP	Mesin	Section	Lokasi	Kendala	Status	Created Date	Last Update	Actions
1	FP0105	CC3	Bubut	D58	Salah Sparepart	ON PROGRESS	2024-02-16 08:29:47	2024-03-18 08:46:44	
2	FP0114	CC3	Machining	D58	Salah Sparepart	CLOSED	2024-03-18 08:09:08	2024-03-18 08:10:07	
3	FP0113	CC3	MC Custom	D58	Sparepart Rusak	CLOSED	2024-03-13 13:49:27	2024-03-13 13:53:56	
4	FP0108	CC1	Bubut	D58	d	CLOSED	2024-03-01 09:40:35	2024-03-06 13:18:22	
5	FP0112	CC3	MC Custom	D58	Salah Sparepart	CLOSED	2024-03-06 13:07:01	2024-03-06 13:18:10	
6	FP0111	CC4	Bubut	D58	Salah Sparepart	OPEN	2024-03-06 11:21:43	2024-03-06 11:21:43	
7	FP0110	CC2	MC Custom	Deltamas	Salah Isi	CLOSED	2024-03-04 17:34:26	2024-03-05 07:55:15	
8	FP0109	CC2	Cutting	D58	Oke	CLOSED	2024-03-04 16:11:45	2024-03-04 16:12:14	
9	FP0107	CC3	Machining	D58	Sparepart	CLOSED	2024-02-26 08:42:17	2024-02-26 08:55:54	
10	FP0106	CC2	MC Custom	D58	Wokeh Slapp	FINISH	2024-02-16 08:37:24	2024-02-16 19:03:47	

Showing 1 to 10 of 27 entries

Action Lihat : (sama dengan tampilan riwayat proses perbaikan di sidebar sales)

The screenshot shows the 'FPP View Form' interface. The sidebar menu includes 'DMS Menu', 'Production', 'Maintenance', 'Dept. Maintenance', and 'Sales'. The main form area contains fields for 'Applicant*', 'Date*', 'Section*', 'Machine*', 'Machine Location*', 'Constraints*', and 'Picture'. Below the form is the 'History Progress Table' with the following data:

No	Follow-up	Checking Schedule	Operator	Due Date	File	Status	Note	Last Update
1			PIC		N/A	OVEN	FPP FORM CREATED	2024-02-16 08:29:47
2			PIC		N/A	ON PROGRESS	BEING FOLLOWED UP	2024-02-16 08:30:05
3			PIC		N/A	ON PROGRESS		2024-02-16 08:30:05
4			PIC		gunung.jpg	ON PROGRESS	BEING FOLLOWED UP	2024-02-16 08:32:48
5		2024-02-16	PIC	2024-02-15	N/A	ON PROGRESS	BEING FOLLOWED UP	2024-02-26 09:20:32
6		2024-02-17	PIC	2024-02-15	N/A	ON PROGRESS	BEING FOLLOWED UP	2024-02-26 09:22:03
7		2024-02-15	PIC	2024-02-15	gunung.jpg	ON PROGRESS	BEING FOLLOWED UP	2024-02-26 11:18:05
8	Wrong Contents	2024-02-15	PIC	2024-02-15	Microsoft Certification.pdf	ON PROGRESS	BEING FOLLOWED UP	2024-03-05 08:04:00
9	Wrong Contents	2024-02-15	PIC	2024-02-15	N/A	ON PROGRESS	BEING FOLLOWED UP	2024-03-12 09:11:43

7. Dibagian dephead maintenance : (halaman blm ada)

Memastikan apakah perbaikan maintenance sudah sesuai. Maka ada button : Confirm dan Finish

a. Confirm ditujukan ke halaman maintenance untuk dilakukan pengecekan ulang, maka status menjadi on progress kembali

B. Finish ditujukan ke halaman section produksi (sidebar productions) untuk di close tiketnya.

Bahwa maintenance sudah melakukan perbaikan dengan benar dan rapi.

8. Close Flow Maintenance Corrective