

From: Priya Sharma (HCSA) <priya.sharma@HCSA.com>
To: Catherine Lee (HCSA) <catherine.lee@HCSA.com>
Cc: David Wong (HCSA) <david.wong@HCSA.com>
Date: Thursday, 20 March 2025 9:00 AM
Subject: RE: Incident - Site C scaffolding fall - investigation update

Catherine,

A key finding has emerged from the investigation records. As per the documentation received this morning, the daily inspection of the scaffold platform where the fall occurred was incomplete at the time of the incident — Bay 4 had not been cleared for use.

This represents a potential failure in the inspection protocol (SOP-CO-003 Section 4.1 — construction site inspection to be completed before work commencement). Work may have proceeded on an uninspected scaffold.

I will include this as a primary contributing factor in the RCA. Initial corrective actions to be raised:

- Immediate 100% scaffold inspection across all active sites
- Reinforcement of pre-work inspection sign-off at morning toolbox talks
- Review of Bay clearance procedures before worker deployment

Full RCA report to follow within the 7 business day window.

Priya Sharma

HSE Supervisor, HSE Department | HCSA

priya.sharma@HCSA.com

From: David Wong (HCSA) <david.wong@HCSA.com>
To: Priya Sharma (HCSA) <priya.sharma@HCSA.com>
Date: Thursday, 20 March 2025 7:45 AM
Subject: RE: Incident - Site C scaffolding fall - IR-62 and inspection record

Priya,

Please find the following attached to this email:

- Incident Report Form IR-62 (completed)
- Daily Inspection Record DSI-CS-90 (morning of 19 March)

Issue noted: the inspection record shows the scaffold at Bay 4 (where the incident occurred) was not signed off this morning. The Safety Officer check was completed for Bays 1–3 only. Bay 4 was marked 'pending — toe board replacement in progress.'

This may be a significant contributing factor.

David Wong

HSE Officer, HSE Department | HCSA

From: Priya Sharma (HCSA) <priya.sharma@HCSA.com>

To: David Wong (HCSA) <david.wong@HCSA.com>

Date: Wednesday, 19 March 2025 2:00 PM

Subject: RE: Incident - Site C scaffolding fall - investigation actions

David,

Classification confirmed as Level 3. Please proceed with the following:

1. Preserve all physical evidence — do not dismantle the scaffolding platform until the investigation team has inspected it.
2. Pull the daily inspection record for the scaffold (Form DSI-CS-90) from this morning — was it completed before 7am?
3. Compile witness statements into the RCA template (Form RCA-70).
4. Submit the written incident report (IR-62) to me by 8:00 AM tomorrow.

I will lead the formal investigation with you and the Site Supervisor. We will convene on site Friday, 21 March at 9am.

Priya

HSE Senior Officer, HSE Department | HCSA

From: Catherine Lee (HCSA) <catherine.lee@HCSA.com>

To: Priya Sharma (HCSA) <priya.sharma@HCSA.com>

Date: Wednesday, 19 March 2025 1:10 PM

Subject: RE: Incident - Site C scaffolding fall - classification assessment

Priya,

Classification as Level 3 confirmed. Well handled.

A few points:

1. Ensure the IC-65 is filed and the written IR-62 is submitted within 24 hours per Level 3 protocol.
2. The RCA must be completed within 7 business days, led by you with Site Supervisor and Safety Officer involved.
3. Please flag corrective actions in Form CAR-100 with target closure dates.

For the investigation — check scaffolding inspection records. If Bay 4 was not signed off this morning under the daily inspection (Document DSI-CS-90), that may be a contributing factor.

Catherine Lee

HSE Senior Officer, HSE Department | HCSA

From: Priya Sharma (HCSA) <priya.sharma@HCSA.com>
To: Catherine Lee (HCSA) <catherine.lee@HCSA.com>
Cc: David Wong (HCSA) <david.wong@HCSA.com>
Date: Wednesday, 19 March 2025 12:00 PM
Subject: RE: Incident - Site C scaffolding fall - classification assessment

Catherine,

Based on the information gathered so far:

- Fall height: 3.2m (exceeds the 3m flag threshold)
- Injury: muscle strain and shoulder contusion — no fracture, no loss of consciousness
- Hospitalisation: <24 hours (same-day discharge after 4-hour observation)
- CCTV: confirms no loss of consciousness at impact
- Medical report: confirms minor injury only

Preliminary classification: Level 3 (hospitalisation <24 hours for observation). The actual outcome does not meet Level 2 criteria.

I note the fall height and potential consequence, however per Section 5.2 of the policy I am issuing classification on Form IC-65 as Level 3 — confirmed

I will initiate the Level 3 investigation (RCA) led by myself with Site Supervisor and Safety Officer.

Written report to follow within 24 hours.

Priya Sharma

HSE Senior Officer, HSE Department | HCSA

From: David Wong (HCSA) <david.wong@HCSA.com>
To: Priya Sharma (HCSA) <priya.sharma@HCSA.com>
Date: Wednesday, 19 March 2025 11:15 AM
Subject: RE: Incident - Site C scaffolding fall - hospital update

Priya,

Hospital update just received. Worker was observed for 4 hours, X-rays show no fractures. Diagnosed with muscle strain and contusion to right shoulder. No loss of consciousness recorded. Discharged same day.

CCTV footage reviewed — no loss of consciousness at the point of impact. Worker was alert and responsive throughout.

I have completed the preliminary incident notification form (INF-95). Two workers and the site foreman have been interviewed — statements are consistent.

David

HSE Officer, HSE Department | HCSA

From: Catherine Lee (HCSA) <catherine.lee@HCSA.com>
To: Priya Sharma (HCSA) <priya.sharma@HCSA.com>
Date: Wednesday, 19 March 2025 8:40 AM
Subject: RE: FW: Incident - Site C scaffolding fall - this morning

Priya,

Understood. Agreed on the borderline flag — fall from height >3m qualifies for HSE Manager review.

Please proceed with Step 2 of the classification process and keep me updated on the hospital outcome.

If the report indicates hospitalisation beyond 24 hours or any loss of consciousness, escalate immediately to Level 2 and notify the HSE Director within the hour.

Catherine Lee

HSE Senior Officer, HSE Department | HCSA

From: Priya Sharma (HCSA) <priya.sharma@HCSA.com>
To: Catherine Lee (HCSA) <catherine.lee@HCSA.com>
Cc: David Wong (HCSA) <david.wong@HCSA.com>
Date: Wednesday, 19 March 2025 8:22 AM
Subject: FW: Incident - Site C scaffolding fall - this morning

Catherine,

Please see the incident notification below. I am treating this as a borderline Level 2/3 case per POL-CO-003 Section 5.2. The fall height (3.2m) exceeds the 3-metre flag threshold in the SOP, regardless of the actual injury outcome at this point.

I will conduct the rapid assessment per the borderline protocol. David has preserved the scene.

Hospital report is pending.

Priya Sharma

HSE Senior Officer, HSE Department | HCSA

From: David Wong (HCSA) <david.wong@HCSA.com>
To: Priya Sharma (HCSA) <priya.sharma@HCSA.com>
Date: Wednesday, 19 March 2025 8:05 AM
Subject: Incident - Site C scaffolding fall - this morning

Priya,

Reporting an incident at Site C (Bukit limau mixed-use block) this morning at approximately 7:20 AM.

Worker Nguyen Van Duc (scaffolding crew) fell from a scaffold platform. He was taken to hospital.

Initial assessment: platform approximately 3.2 metres above ground level. Worker landed on compacted earth. He was conscious, complaining of pain in his lower back and right shoulder.

I have preserved the scene and taken photos. Awaiting hospital update.

David Wong

HSE Officer, HSE Department | HCSA

david.wong@HCSA.com