

Test 2 - 999999

Audit Details

Auditor Name	Auditor 20-06
Date of Audit	01-07-2026
Time of Audit	17:28 PM

Checklist

Sr. No	Checklist Point	Response / Remarks
1	Vehicle No	GJ01AZ0001
2	Vehicle Type	TEMPO
3	Load Size(ton.)	5
4	Vehicle Condition	GOOD
5	Insurance	NOT AVAILABLE
6	Log Sheet Entry	NOT AVAILABLE
7	Upload Photos	