

MONONGAHELA UTILITY CONSULTANTS
DISTRIBUTION MAIN CONDITION ASSESSMENT

Report reference: CA-2025-0257

Date of inspection: 2025-07-19

Inspector: R.Valanos, P.E.

Client: Three Rivers Water Authority

1. SCOPE

Visual and limited non-destructive assessment of distribution main segment WM-1398, located on Penn Avenue in the Lawrenceville area of the PZ-HL1 pressure zone. The segment is a 16-inch cast iron main of approximately 233 ft, originally installed in 1944.

2. METHOD

Access was obtained by test pit at one location. The exposed section was cleaned and examined visually. Wall thickness was assessed by ultrasonic spot readings where surface condition permitted. No internal inspection was performed.

3. OBSERVATIONS

Heavy tuberculation with significant loss of effective diameter. Flushing recommended prior to any hydraulic assessment.

No active leak was detected at the time of inspection. Soil at pipe depth was damp with poor drainage.

4. FINDING

Condition classification: SEVERE

Primary observation: internal tuberculation

5. RECOMMENDATION

Prioritise this segment for replacement planning. Re-inspect within 12 months if replacement cannot be scheduled.

This assessment reflects the condition of the exposed section only and should not be taken as representative of the entire segment.