

ALLEGHENY PIPELINE SERVICES
DISTRIBUTION MAIN CONDITION ASSESSMENT

Report reference: CA-2026-0274

Date of inspection: 2026-01-26

Inspector: M. Okonkwo, P.E.

Client: Three Rivers Water Authority

1. SCOPE

Visual and limited non-destructive assessment of distribution main segment WM-2124, located on Centre Avenue in the East Liberty area of the PZ-GAR pressure zone. The segment is a 16-inch cast iron main of approximately 399 ft, originally installed in 1940.

2. METHOD

Access was obtained by test pit at one location. The exposed section was cleaned and examined visually. Wall thickness was assessed by ultrasonic spot readings where surface condition permitted. No internal inspection was performed.

3. OBSERVATIONS

Repeated prior excavation with poor reinstatement. Segment has been disturbed multiple times.

No active leak observed. Soil at pipe depth was damp with poor drainage.

4. FINDING

Condition classification: SEVERE

Primary observation: prior excavation

5. RECOMMENDATION

Prioritise this segment for replacement planning. Re-inspect within 12 months if replacement cannot be scheduled.

This assessment reflects the condition of the exposed section only and should not be taken as representative of the entire segment.