

MONONGAHELA UTILITY CONSULTANTS
DISTRIBUTION MAIN CONDITION ASSESSMENT

Report reference: CA-2023-0186

Date of inspection: 2023-03-05

Inspector: J. Whitmore

Client: Three Rivers Water Authority

1. SCOPE

Visual and limited non-destructive assessment of distribution main segment WM-2881, located on Whited Street in the Brookline area of the PZ-BRS pressure zone. The segment is a 8-inch cast iron main of approximately 283 ft, originally installed in 1951.

2. METHOD

Access was obtained by test pit at one location. The exposed section was cleaned and examined visually. Wall thickness was assessed by ultrasonic spot readings where surface condition permitted. No internal inspection was performed.

3. OBSERVATIONS

Sustained leakage at the joint with visible washout of surrounding bedding material.

No active leak was detected at the time of inspection. Soil at pipe depth was damp with poor drainage.

4. FINDING

Condition classification: SEVERE

Primary observation: joint leakage

5. RECOMMENDATION

Prioritise this segment for replacement planning. Re-inspect within 12 months if replacement cannot be scheduled.

This assessment reflects the condition of the exposed section only and should not be taken as representative of the entire segment.