

VERDICT: PARTIAL MATCH (50% MATCH CONFIDENCE)

Partial consistency detected (50% match). Detected damages partially overlap with claimed description, but discrepancies exist in severity or secondary parts. Desk review recommended.

Policyholder Information	Vehicle Details
Name: Sarah Jenkins Email: policyholder@secureclaim.ai Claim Type: Collision Damage	Model: Hyundai i20 Asta Registration: TN-01-MJ-8821 Claimed Part: Front Left Door

Claim Discrepancy & Cross-Check Matrix

Parameter	Claimed by Policyholder	Detected by AI Vision	Status
Damaged Component	Front Left Door	Windshield, Front Bumper	Discrepancy
Damage Severity	Severe	Moderate, Minor	Differing
Description Summary	Brushed against a parking garage pillar while parallel parking, causing a dent and scratch...	2 damage region(s) identified with segmentation masks	50% Alignment


Itemized Damage & Repair Cost Breakdown

#	Part	Damage Type	Severity	AI Confidence	Est. Cost Range
1	Front Bumper	Dent	Moderate	91%	INR 8,000 – 18,000
2	Windshield	Bumper Damage	Minor	92%	INR 3,000 – 12,000
TOTAL	All Identified Damage				INR 11,000 – 30,000

Photographic Evidence & AI Segmentation Overlay

Uploaded Photo (Original)

AI Damage Segmentation Mask



DIGITALLY VERIFIED

Certified by SecureClaim AI Neural Vision Engine v2.4
Cryptographic Checksum: SHA256-OK

Settlement Recommendation: Partial Match

This assessment is generated automatically according to Underwriting
RuleSet 2026.4.