

VERDICT: PARTIAL MATCH (49% MATCH CONFIDENCE)

Partial consistency detected (49% match). Detected damages partially overlap with claimed description, but discrepancies exist in severity or secondary parts. Desk review recommended.

Policyholder Information	Vehicle Details
Name: KISHORE Email: kishoreg2605@gmail.com Claim Type: Collision Damage	Model: Hyundai i20 Asta Registration: TN-01-MJ-8821 Claimed Part: Front Bumper

Claim Discrepancy & Cross-Check Matrix

Parameter	Claimed by Policyholder	Detected by AI Vision	Status
Damaged Component	Front Bumper	Front Bumper, Front Left Fender, Headlight, Rear Bumper, Front Right Fender	Matched
Damage Severity	Minor	Moderate, Minor, Severe	Consistent
Description Summary	Brushed against a parking garage pillar while parallel parking, causing a dent and scratch...	6 damage region(s) identified with segmentation masks	49% Alignment

Itemized Damage & Repair Cost Breakdown

#	Part	Damage Type	Severity	AI Confidence	Est. Cost Range
1	Front Bumper	Dent	Severe	93%	INR 22,000 – 45,000
2	Front Left Fender	Dent	Minor	82%	INR 2,500 – 6,000
3	Headlight	Crack	Moderate	84%	INR 6,000 – 15,000
4	Front Bumper	Dent	Minor	92%	INR 2,500 – 6,000
5	Front Right Fender	Mirror Damage	Minor	82%	INR 3,000 – 12,000
6	Rear Bumper	Panel Deformation	Moderate	95%	INR 12,000 – 35,000
TOTAL All Identified Damage					INR 48,000 – 119,000

Photographic Evidence & AI Segmentation Overlay

Uploaded Photo (Original)

AI Damage Segmentation Mask



DIGITALLY VERIFIED

Certified by SecureClaim AI Neural Vision Engine v2.4
Cryptographic Checksum: SHA256-OK

Settlement Recommendation: Partial Match

This assessment is generated automatically according to Underwriting
RuleSet 2026.4.