

VERDICT: MATCH (85% MATCH CONFIDENCE)

AI assessment verified: Claimed damage on Front Bumper strongly aligns with detected damage patterns (85% confidence match). Proceed to automated settlement.

Policyholder Information	Vehicle Details
Name: Test User Email: test@test.com Claim Type: Collision Damage	Model: Honda City Registration: KA-01-XX-1234 Claimed Part: Front Bumper

Claim Discrepancy & Cross-Check Matrix

Parameter	Claimed by Policyholder	Detected by AI Vision	Status
Damaged Component	Front Bumper	Front Bumper	Matched
Damage Severity	Minor	Minor	Consistent
Description Summary	Dent on bumper	1 damage region(s) identified with segmentation masks	85% Alignment

Itemized Damage & Repair Cost Breakdown

#	Part	Damage Type	Severity	AI Confidence	Est. Cost Range
1	Front Bumper	Dent	Minor	89%	INR 2,500 – 6,000
TOTAL	All Identified Damage				INR 2,500 – 6,000

Photographic Evidence & AI Segmentation Overlay

Uploaded Photo (Original)

AI Damage Segmentation Mask



DIGITALLY VERIFIED

Certified by SecureClaim AI Neural Vision Engine v2.4
Cryptographic Checksum: SHA256-OK

Settlement Recommendation: Match

This assessment is generated automatically according to Underwriting
RuleSet 2026.4.