

VERDICT: MATCH (88% MATCH CONFIDENCE)

AI damage analysis matches claimed incident. Minor front bumper dent and paint scratches verified.

Policyholder Information	Vehicle Details
Name: Alex Johnson Email: user@secureclaim.com Claim Type: Collision Damage	Model: 2023 Honda Civic Registration: KA-01-MJ-8821 Claimed Part: Front Bumper

Claim Discrepancy & Cross-Check Matrix

Parameter	Claimed by Policyholder	Detected by AI Vision	Status
Damaged Component	Front Bumper	Windshield, Front Bumper	Matched
Damage Severity	Minor	Severe, Minor	Consistent
Description Summary	Vehicle brushed against a low pillar during parallel parking, causing a dent and scratches...	2 damage region(s) identified with segmentation masks	88% Alignment


Itemized Damage & Repair Cost Breakdown

#	Part	Damage Type	Severity	AI Confidence	Est. Cost Range
1	Front Bumper	Dent	Severe	90%	\$0 – \$0
2	Windshield	Scratch	Minor	82%	\$0 – \$0
TOTAL					All Identified Damage
					\$7,000 – \$13,500

Photographic Evidence & AI Segmentation Overlay

Uploaded Photo (Original)

AI Damage Segmentation Mask



DIGITALLY VERIFIED

Certified by SecureClaim AI Neural Vision Engine v2.4
Cryptographic Checksum: SHA256-OK

Settlement Recommendation: Match

This assessment is generated automatically according to Underwriting
RuleSet 2026.4.