

VERDICT: PARTIAL MATCH (62% MATCH CONFIDENCE)

Hood panel deformation verified. Secondary damage detected on front left fender requiring surveyor verification.

Policyholder Information	Vehicle Details
Name: Alex Johnson Email: user@secureclaim.com Claim Type: Collision Damage	Model: 2022 Hyundai Creta Registration: MH-14-GH-3341 Claimed Part: Hood

Claim Discrepancy & Cross-Check Matrix

Parameter	Claimed by Policyholder	Detected by AI Vision	Status
Damaged Component	Hood	Hood	Matched
Damage Severity	Moderate	Minor	Differing
Description Summary	Object fell from construction site on the car hood and slightly cracked the windshield.	1 damage region(s) identified with segmentation masks	62% Alignment


Itemized Damage & Repair Cost Breakdown

#	Part	Damage Type	Severity	AI Confidence	Est. Cost Range
1	Hood	Crack	Minor	97%	\$0 – \$0
TO TA L	All Identified Damage				\$22,000 – \$45,000

Photographic Evidence & AI Segmentation Overlay

Uploaded Photo (Original)

AI Damage Segmentation Mask



DIGITALLY VERIFIED

Certified by SecureClaim AI Neural Vision Engine v2.4
Cryptographic Checksum: SHA256-OK

Settlement Recommendation: Partial Match

This assessment is generated automatically according to Underwriting
RuleSet 2026.4.