

VERDICT: FLAGGED (28% MATCH CONFIDENCE)

Severe discrepancy detected. Claimed minor side mirror damage does not match severe rear structure deformation.

Policyholder Information	Vehicle Details
Name: Alex Johnson Email: user@secureclaim.com Claim Type: Collision Damage	Model: 2024 Toyota Camry Registration: DL-03-CC-9912 Claimed Part: Side Mirror

Claim Discrepancy & Cross-Check Matrix

Parameter	Claimed by Policyholder	Detected by AI Vision	Status
Damaged Component	Side Mirror	Rear Bumper	Discrepancy
Damage Severity	Minor	Minor	Consistent
Description Summary	Claimant reported minor mirror scratch, but image shows heavy rear bumper crumple and quar...	1 damage region(s) identified with segmentation masks	28% Alignment


Itemized Damage & Repair Cost Breakdown

#	Part	Damage Type	Severity	AI Confidence	Est. Cost Range
1	Rear Bumper	Scratch	Minor	89%	\$0 – \$0
TO TA L	All Identified Damage				\$38,000 – \$85,000

Photographic Evidence & AI Segmentation Overlay

Uploaded Photo (Original)

AI Damage Segmentation Mask



DIGITALLY VERIFIED

Certified by SecureClaim AI Neural Vision Engine v2.4
Cryptographic Checksum: SHA256-OK

Settlement Recommendation: Flagged

This assessment is generated automatically according to Underwriting
RuleSet 2026.4.