

VERDICT: PARTIAL MATCH (52% MATCH CONFIDENCE)

Partial consistency detected (52% match). Detected damages partially overlap with claimed description, but discrepancies exist in severity or secondary parts. Desk review recommended.

Policyholder Information	Vehicle Details
Name: Alex Johnson Email: user@secureclaim.com Claim Type: Collision Damage	Model: 2023 Honda Civic Sedan Registration: KA-01-MJ-8821 Claimed Part: Front Bumper

Claim Discrepancy & Cross-Check Matrix

Parameter	Claimed by Policyholder	Detected by AI Vision	Status
Damaged Component	Front Bumper	Front Bumper, Rear Right Door	Matched
Damage Severity	Moderate	Moderate, Minor	Consistent
Description Summary	Brushed against a parking garage pillar while parallel parking, causing a dent and scratch...	2 damage region(s) identified with segmentation masks	52% Alignment


Itemized Damage & Repair Cost Breakdown

#	Part	Damage Type	Severity	AI Confidence	Est. Cost Range
1	Front Bumper	Dent	Moderate	93%	\$12,000 – \$24,000
2	Rear Right Door	Paint Damage	Minor	91%	\$3,000 – \$12,000
TOTAL	All Identified Damage				\$15,000 – \$36,000

Photographic Evidence & AI Segmentation Overlay

Uploaded Photo (Original)

AI Damage Segmentation Mask



DIGITALLY VERIFIED

Certified by SecureClaim AI Neural Vision Engine v2.4
Cryptographic Checksum: SHA256-OK

Settlement Recommendation: Partial Match

This assessment is generated automatically according to Underwriting
RuleSet 2026.4.