



Avantgarde Inc FZCO

P.O. Box: 54831
JW 21A, OASIS-THREE
United Arab Emirates
Tel: +971 4 2594192
Fax: +971 4 2502766
Web: www.avantgardeinc.com

Service Request Form

SERVICE INSTANCE

Date: 24-Jun-2021

Time: 16:49

Site Name: SAGAMU

Country: NIGERIA

CUSTOMER INFORMATION

Company Name: LAFARGE AFRICA PLC

Operator's Name: OLUTAYO OLUSEGUN

Contact Person: ADAMU FRANCIS

Operator's Number: +234 701 583 4573

Email: francis.adamu@lafargeholcim.com

Operator's Email: olutayo.olusegun@lafargeholcim.com

INSTRUMENT INFORMATION

Machine Model No.: Optim X

Machine Serial No.: 2073

X-Ray Generator:

Sample Handling Type:

BREAKDOWN INFORMATION

Type of Breakdown:

Is this recurring Problem: ☐ Yes ☒ No

If Yes,

Breakdown occurrence details:

The instrument was started and configured but to power On the x-ray tube failed

Alarm details with print screen:

#8196— Desired voltage(kv) to low and INTERLOCK Is displayed on the instrument

Action taken to resolve:

One of the suggested board when Thermo Service engineer was on site in 2019 yet the instrument failed to power ON

Current Instrument Status:

We are unable to use the instrument

Complaint Registrar Name: OLUTAYO OLUSEGUN

Phone: +234 701 583 4573

"The Breakdown service request must be sent along with the report for problems assessment"

Nurturing Partnership

- File
 - Login
 - Log Off [XRF]
 - Operational Mode
 - Offline Mode
 - Full Backup
 - Exit
- Analysis and Data
 - Raw Data Analysis [F5]
 - Log On RAW
 - SAMPLE FILE
 - CURRENT FILE
 - CURRENT FILE
 - C3 TEST
- Batches [F11]
 - Qualitative Analysis
 - View Results [F9]
- Measure Control Sample
 - Standardize [F3]
 - Measure Type Standard
 - Measure SCT Samples
- Operation Setup
 - Measure Calibration
 - Two Theta Calculator
 - Tools
- Monitoring and Troubleshooting
 - Instrument Alarm
 - Monitoring Peripherals
 - C:\IPMS\IPMS.D
 - KS
 - Koel 31000
 - My CSV file
 - Printer 1
 - QMS_P000
 - System Messages
 - Diagnostic Log
 - Operational Log
 - ICS_Log
 - MTA_Log
 - Automation_Log
 - UnQueue_Log
 - Check Detector
 - Run Energy Profile
 - Investigate Energy Profile
- Views
 - Explorer Bar
 - Icon Panel
 - Reaction Features at Start
 - Popup Instrument Alarms
 - Show Analysis Progress Window
- Help
 - Help
 - About

Warning #333: X-ray power supply interlock open
Fatal #4196: Detector voltage (V) too low
Warning #452: Tank temperature too low

Instrument Status

Select Status Reading Parameters

Monitor Selected

PDF Output

Exit

Status	Description	Value	Min	Max
PC_Vac	Primary chamber pressure	23871.18 [Pa]	0	32000
SF_Vac	Spectrometer pressure	6.808176 [Pa]	0	20
BackTemp	Electronic rack temperature	33.573 [C]	20	50
PumpTm	Dumping time of last loaded sample	4 [s]	1	120
TankTemp	Spectrometer tank temperature	35.97 [C]	20	40
ITCPressure	ITC pressure	105676 [Pa]	30000	115000
ITCFlow	ITC gas flow	6210 [ul/min]	4000	40000
XGpEv	XGTO 45 V	5.039 [V]	4.7	6.4
XGp24V	X-ray tube voltage	24.012 [kV]	22	26
KV	X-ray tube current	0.141 [mA]	-0.5	0.5
ak	X-ray tube temperature	0.512 [C]	-0.5	5.1
Tubing	X-ray tube filament current	28.1 [A]	1	25
Filament	XPSXP +24 V	23.918 [V]	20	26
XGSP24V	X-ray tube arc count	1 [I]	0	200
KrayArcs	Laboratory ambient temperature	23.2 [C]	15	30
LabTemp	Air temperature near X-ray generator	26.3 [C]	15	45
XGactTemp	Main voltage (230 V : L1 phase)	229.074 [V]	200	230
MainVol	XGP -5 V	-5.692 [V]	-6	-4.8
XGP-5V	Geolo detector high voltage	< 1.453463 [V]	1300	2400
C_RVB				

Chronological View [Selected: 1 / 999]

Analysis	Search	Test Search	Ready
1	2	3	4
5	6	7	8
9	10	11	12
13	14	15	16
17	18	19	20
21	22	23	24
25	26	27	28
29	30	31	32
33	34	35	36
37	38	39	40
41	42	43	44
45	46	47	48
49	50	51	52
53	54	55	56
57	58	59	60
61	62	63	64
65	66	67	68
69	70	71	72
73	74	75	76
77	78	79	80
81	82	83	84
85	86	87	88
89	90	91	92
93	94	95	96
97	98	99	100

Analysis Header Details

Analysis Type	NA
101	101
Method	101
Average Type	St
Sample Pos. h1	Cu
Sample Pos. h2	Cu
Recalculated	
Graph Check	
SQC Check	