

VEHICLE HEALTH REPORT

1. Vehicle Information

Vehicle Number : MH12AB1203
Owner Name : Atharv Rupde
Contact Number : 9876543203
Model : Creta
Fuel Type : Petrol
Color : Titan Grey
Manufacturing Year : 2023
Registration Date : 22/06/2023

2. Overall Vehicle Health

Status : **Critical**


Alert : Immediate Service Required

3. Sensor Health Details

Sensor	Value	Status
Engine Temperature	88	Healthy
Engine Oil Life	85	Healthy
Engine Oil Temperature	103	Healthy
Front Brake Wear	75	Warning
Rear Brake Wear	45	Healthy
Brake Fluid Condition	35	Critical
Battery Voltage	12.8	Healthy
Charging Voltage	13.2	Warning
Mileage Since Last Service	9500	Warning
Engine RPM	5000	Critical
Coolant Temperature	90	Healthy
Engine Hours	4200	Critical

4. Vehicle Analytics

Sensor Health Distribution



5. Recommended Actions

- Engine Temperature : Engine temperature is operating within normal range.
- Engine Oil Life : Engine oil condition is healthy.
- Engine Oil Temperature : Engine oil temperature is normal.
- Front Brake Wear : Schedule front brake inspection.
- Rear Brake Wear : Rear brake condition is good.
- Brake Fluid Condition : Replace brake fluid immediately.
- Battery Voltage : Battery health is normal.
- Charging Voltage : Inspect alternator and charging system.
- Mileage Since Last Service : Schedule routine maintenance soon.
- Engine RPM : Inspect engine operation immediately.
- Coolant Temperature : Coolant temperature is normal.
- Engine Hours : Engine requires immediate maintenance due to excessive usage.

Generated On : 30-Jul-2026 10:07 AM

Vehicle Wear & Tear Prediction System