



Customer: **2155 8001 - Union Tank Car Co.**
 Contact: **Shop Approvals**
 E-Mail: **shopappr@utlx.com**

Approval
LBU BLANKET APPROV/
 Sep/29/2020
 NONE

Shop
047600 - SARNIA
 P: (519)332-8000
 F: (519)332-8003

Car Number: **UTLX 678133**
 Kind of Car: **Tank**

Arrival Date: **Mar/16/2020**
 Defect Card # :

Release Date: **Sep/17/2020**
 Card Date:

Location	Qty	Cond Code	Job Code Applied	Description	Job Code Removed	Why Made	Resp	Labour	Material	Net Charge	Rev
AR	1.0	1	4099 RR	TC-128 ROLLED PLATE	4099 RR	06	3	0.00	718.25	718.25	
AR	720.0	1	4204 RN	SHEET,11 GA.STEEL A-569 ROLLED TO RAD. 0	4204 RN	06	3	0.00	1,548.36	1,548.36	
AR	1.0	1	4204 RR	HEATER COIL KIT	4244 RR	06	3	0.00	25.50	25.50	
AR	720.0	1	4244 RN	TANK JACKET STEEL CREDITS	4244 RN	09	3	0.00	-67.32	-67.32	
	210.0	1	4244 RR	TANK INSERT STEEL CREDIT	4244 RR	09	3	0.00	-19.64	-19.64	
AR	1.0	0	4450 RM	RENEW TANK INSULATION	4450 RM	09	3	126.40	0.00	126.40	
AR	1.0	0	4450 RR	STRESS RELIEF AFFECTED AREA	4450 RR	09	3	3,836.05	0.00	3,836.05	
C	1.0	0	4450 RR	R&R BOT. OUT.VLV. & NOZZLE W/BODY GASKET	4450 RR	09	3	189.60	0.00	189.60	
	1.0	0	4450 RR	TEST HEATER COILS	4450 RR	09	3	126.40	0.00	126.40	
	0.3	0	4450 RR	FROM TOP: VESSEL ENTRY TEST, PSP-S-24.	4450 RR	09	3	37.92	0.00	37.92	
	0.3	0	4450 RR	FROM TOP: VESSEL ENTRY TEST, PSP-S-24.	4450 RR	09	3	37.92	0.00	37.92	
AR	1.0	0	4450 RR	UT AFFECTED AREA	4450 RR	09	3	408.00	0.00	408.00	
AR	2.0	0	4450 RR	MT REPAIR (1) BEFORE STRESS RELIEF _____	4450 RR	09	3	252.80	0.00	252.80	
AR	8.0	0	4450 RR	REINFORCE TANK SHELL INTERIOR FOR INSERT REMOVAL	4450 RR	09	3	1,011.20	0.00	1,011.20	
C	1.0	0	4450 RR	REBUILD/TEST 4" UTC FULL PORT LOW PROFIE VALVE-TFE	4450 RR	09	3	252.80	172.09	424.89	
	0.3	0	4450 RR	FROM TOP: VESSEL ENTRY TEST, PSP-S-24.	4450 RR	09	3	37.92	0.00	37.92	
	0.3	0	4450 RR	FROM TOP: VESSEL ENTRY TEST, PSP-S-24.	4450 RR	09	3	37.92	0.00	37.92	
AR	4.0	0	4450 RR	STRAIGHTEN SECTION TANK SHELL	4450 RR	09	3	505.60	0.00	505.60	
AR	144.0	1	4602 RN	PRIME ,PAINT ,DECAL	4602 RN	09	3	241.13	29.38	270.51	
AR	504.0	0	4800 RN	FILLET WELD TANK JACKET	4800 RN	09	3	2,548.22	0.00	2,548.22	
AR	96.0	0	4800 RR	FILLET WELD SECTION HEATER COIL	4800 RR	09	3	485.38	0.00	485.38	
AR	20.0	0	4808 RR	BUTT WELD SECTION HEATER COIL	4808 RR	09	3	136.51	0.00	136.51	
AR	160.0	0	4808 RR	BUTT WELD TANK SHELL INSERT	4808 RR	09	3	1,092.10	0.00	1,092.10	
C	1.0	1	4999 KY	GASKET,CYCLETIGHT -7AE ,1/8"X19-1/2X 21-5/8 1	4999 KY	09	3	37.92	384.06	421.98	
C	1.0	1	4999 PN	GASKET,1/4X3-1/2X5-1/8 GARLOCK 1	4999 PN	09	3	0.00	207.31	207.31	



Customer: **2155 8001 - Union Tank Car Co.**
 Contact: **Shop Approvals**
 E-Mail: **shopappr@utlx.com**

Approval
LBU BLANKET APPROV/
 Sep/29/2020
 NONE

Shop
047600 - SARNIA
 P: (519)332-8000
 F: (519)332-8003

Car Number: **UTLX 678133** Arrival Date: **Mar/16/2020**
 Kind of Car: **Tank** Defect Card # :

Release Date: **Sep/17/2020**
 Card Date:

Location	Qty	Cond Code	Job Code Applied	Description	Job Code Removed	Why Made	Resp	Labour	Material	Net Charge	Rev
AR	144.0	1	4999 RM	INSULATION,CERAMIC FIBER,.65 X 4'X 31.5' 0	4999 RM	09	3	0.00	170.14	170.14	
AR	1.0	1	4999 RN	DECAL LIST	4999 RN	09	3	0.00	33.41	33.41	
AR	1.0	1	4999 RN	DECAL,"REQUALIFICATION"PER AAR CPC-1071 0	4999 RN	09	3	0.00	30.67	30.67	
C	1.0	1	4999 SB	NUT,LOCK HX 1-1/8-12UNC-2B STEEL 1	4999 SB	09	3	0.00	6.68	6.68	
C	1.0	1	4999 SB	GASKET,PINWHEEL DESIGN 1/8X4-7/8X5-3/4 1	4999 SB	09	3	0.00	97.51	97.51	
C	1.0	0	8008	CLEAN TANK - LUB/CRUDE OIL	8008	09	3	3,337.62	0.00	3,337.62	

Labour	Material	Total
14,739.41	3,336.40	18,075.81 US