



# INSPECTION REPORT

Madhubn Colony  
8-7-1

Prepared for  
**krishna**



Inspection Date  
**1/2/2026**

Inspected By  
**Saikrishna**  
Verified by: Admin

---

# Disclaimer

**Trinetra** is a brand of NS Property Guide Advisors Private Limited providing professional visual property inspection services.

This inspection is non-invasive and limited to visible conditions observed on the inspection date.

## Excluded Services

- ▶ Structural, geotechnical and soil analysis
- ▶ Electrical and plumbing performance testing
- ▶ Indoor air quality, mold and pest inspection
- ▶ Waterproofing, drainage and leakage testing
- ▶ Legal, statutory and code compliance

## Summary



**100%**

Overall Unit  
Health

**10.0**

bd

## II. Area Check

	 DIMENSION (FT × FT)	 AREA (SQ FT)
BD	22 × 22	484.00
Total		0.00

## Quality Check

No Issues Found - Property in Good  
Condition ✓

### Water Quality

PH LEVEL



**7**

Range: 6.5 - 8.5 ✓







TDS








**186** mg/L

Less than 500 mg/L (desirable) ✓






## IV. Dimensions Check

	 FLOORING	 DOOR HEIGHT	 CEILING HEIGHT	 WINDOW DIMENSION	 TILES	 RAILING HEIGHT
BD	Select Option	—	—	—	—	Select Option

## V. Material Check

	 FLOORING	 WALL FINISH	 DOOR	 WINDOWS	 RAILING
BD	Select Option	Select Option	Select Option	Select Option	Select Option

## VI. Brand Check

	 SWITCHBOARD	 FAN	 LIGHT	 WINDOWS	 AC
BD	Select Brand	Select Brand	Select Brand	Select Brand	Select Brand



