



INSPECTION REPORT

jubilee hills

Prepared for

prasad



Inspection Date

1/2/2026

Inspected By

Saikrishna

Verified by: Admin

Disclaimer

Trinetra is a brand of NS Property Guide Advisors Private Limited providing professional visual property inspection services.

This inspection is non-invasive and limited to visible conditions observed on the inspection date.

Excluded Services

- ▶ Structural, geotechnical and soil analysis
- ▶ Electrical and plumbing performance testing
- ▶ Indoor air quality, mold and pest inspection
- ▶ Waterproofing, drainage and leakage testing
- ▶ Legal, statutory and code compliance

Summary



100%

Overall Unit
Health

10.0

Bedroom1

II. Area Check

	 DIMENSION (FT × FT)	 AREA (SQ FT)
BEDROOM1	44 × 22	968.00
	44 × 44	1936.00
Total		0.00

Quality Check

No Issues Found - Property in Good
Condition ✓

Water Quality

PH LEVEL



7

Range: 6.5 - 8.5 ✓







TDS








186 mg/L

Less than 500 mg/L (desirable) ✓






IV. Dimensions Check

	 FLOORING	 DOOR HEIGHT	 CEILING HEIGHT	 WINDOW DIMENSION	 TILES	 RAILING HEIGHT
BEDROOM1	Select Option	—	—	—	—	Select Option

V. Material Check

	 FLOORING	 WALL FINISH	 DOOR	 WINDOWS	 RAILING
BEDROOM1	Select Option	Select Option	Select Option	Select Option	Select Option

VI. Brand Check

	 SWITCHBOARD	 FAN	 LIGHT	 WINDOWS	 AC
BEDROOM1	Select Brand	Select Brand	Select Brand	Select Brand	Select Brand

