



INSPECTION REPORT

jubilee hills

Prepared for

prasad



Inspection Date

1/2/2026

Inspected By

Saikrishna

Verified by: Admin

Disclaimer

Trinetra is a brand of NS Property Guide Advisors Private Limited providing professional visual property inspection services.

This inspection is non-invasive and limited to visible conditions observed on the inspection date.

Excluded Services

- ▶ Structural, geotechnical and soil analysis
- ▶ Electrical and plumbing performance testing
- ▶ Indoor air quality, mold and pest inspection
- ▶ Waterproofing, drainage and leakage testing
- ▶ Legal, statutory and code compliance

Summary

100%

Overall Unit
Health

100.0

Bedroom1

II. Area Check

	 DIMENSION (FT × FT)	 AREA (SQ FT)
BEDROOM1	0 × 0	0.00
Total		0.00

Quality Check

No Issues Found - Property in Good
Condition ✓

Water Quality

PH LEVEL



7

Range: 6.5 - 8.5 ✓







TDS








186 mg/L

Less than 500 mg/L (desirable) ✓






IV. Dimensions Check

	 FLOORING	 DOOR HEIGHT	 CEILING HEIGHT	 WINDOW DIMENSION	 TILES	 RAILING HEIGHT
BEDROOM1	—	—	—	—	—	NA

V. Material Check

	 FLOORING	 WALL FINISH	 DOOR	 WINDOWS	 RAILING
BEDROOM1	—	—	—	—	—

VI. Brand Check

	 SWITCHBOARD	 FAN	 LIGHT	 WINDOWS	 AC
BEDROOM1	—	—	—	—	—

