

INSPECTION REPORT

2nd floor, Krishna Towers, 100 ft road, Madhapur, Hyderabad

Prepared for

Rainbow Villas



Inspection Date

20/2/2026

Inspected By

Charan

Verified by: Admin

Disclaimer

Trinetra is a brand of NS Property Guide Advisors Private Limited providing professional visual property inspection services.

This inspection is non-invasive and limited to visible conditions observed on the inspection date.


Excluded Services

- ▶ Structural, geotechnical and soil analysis
- ▶ Electrical and plumbing performance testing
- ▶ Indoor air quality, mold and pest inspection
- ▶ Waterproofing, drainage and leakage testing
- ▶ Legal, statutory and code compliance


II. Area Check

	 DIMENSION (FT × FT)	 AREA (SQ FT)
LIVING ROOM	10.56 × 14	147.84
KITCHEN	0 × 0	0.00
ROOM	0 × 0	0.00
Total		147.84

Quality Check



Water Quality



IV. Dimensions Check

	 FLOORING	 DOOR HEIGHT	 CEILING HEIGHT	 WINDOW DIMENSION	 TILES	 RAILING HEIGHT
LIVING ROOM	Tile	ft × ft	12ft	3ft × 3ft	4ft × 4ft	Select Option
KITCHEN	—	7ft × 4ft	12ft	5ft × 5ft	4ft × 4ft	Select Option
ROOM	—	—	—	—	—	Select Option


V. Material Check

	 FLOORING	 WALL FINISH	 DOOR	 WINDOWS	 RAILING	 REMARKS
LIVING ROOM	Tile	Paint	Select Option	Select Option	Select Option	—
KITCHEN	Tile	Wallpaper	Select Option	Select Option	Select Option	—
ROOM	Select Option	Select Option	Select Option	Select Option	Select Option	—

VI. Brand Check

	 SWITCHBOARD	 FAN	 LIGHT	 WINDOWS	 AC
LIVING ROOM	Legrand	Crompton	Havells	Wooden	Hitachi
KITCHEN	Schneider Electric	Crompton	Philips	Aluminium	Select Brand
ROOM	Select Brand	Select Brand	Select Brand	Select Brand	Select Brand

ITEM WISE SUMMARY



QUALITY CHECK: KITCHEN

S. NO.	ISSUE	PICTURE
1	Testing the functionality	
2	Photo Log	

ITEM WISE SUMMARY

