DAMAGEGENX

Multi-Vehicle Damage Assessment Platform

Vehicle Inspection Report

Deep Learning · IoT Sensor Fusion · Hidden-Damage Risk Prediction

Inspection ID	INS-035148
Generated on	05 Oct 2026 · 03:51 UTC
Report type	AI-Assisted Damage Assessment
Prepared by	DamageGenX System

This report is generated by an AI-assisted inspection system. Hidden-damage output is a risk estimate and does not replace professional mechanical inspection.

1. Damage Summary

Dominant Damage	Scratch
Fused Severity	7/100 · Minor
Total Detections	1
Views Analyzed	3 / 5
Vehicle Type	Sedan
Primary Component	Front Bumper

Detected Damage Classes

Damage Class	Count	Percentage
Scratch	1	100%

2. IoT Sensor Data

Impact Force	3.2 G
Rotation	80 °/s
GPS Latitude	19.6538
GPS Longitude	72.6391
Data Source	Accelerometer · Gyroscope · GPS

3. Hidden-Damage Risk Assessment

LOW

Risk Score: 25%

Recommendation: No immediate hidden damage concern.

Note: Hidden-damage output is a risk estimate based on visible damage and sensor data. It is not a direct detection of internal damage. Professional inspection is advised when the risk level is High or Critical.

4. Repair Recommendation & Cost Estimate

Recommended Action	REPAINT
Component	Front Bumper
Description	Surface repainting required.
Priority	Minor

Estimated Cost Range: INR 14,556 – 21,406

This is a system-generated estimate. Actual repair costs may vary by location, workshop, and parts availability.

5. Annotated Views



Front



Left



Rear

6. Evidence Integrity

Front	EV-8E33235D9E · sha256:4ad5244cb6e1bf4d…
Left	EV-F489BF43B5 · sha256:6985453809989f7b…
Rear	EV-11DB964240 · sha256:a676c72a9a9412ca…

Each uploaded file receives a unique evidence ID and SHA-256 hash at upload time. Any post-upload modification would produce a different hash.

Disclaimer

This report is generated by DamageGenX, an AI-assisted vehicle inspection platform. Detected damage, severity estimation, hidden-damage risk, and cost estimates are algorithmic outputs and may not be fully accurate. This document does not replace professional mechanical inspection or a formal repair quotation.

© 2026 DamageGenX · Deep Learning + IoT Vehicle Inspection System