CAR-O-LINER® Service Order Request Form (SORF)

(not to be used for Credit Returns)

Instructions:

1. Submit one Form via Email (Ticket) per Main Unit Serial Number.
2. Attach any Signed Slide Rental or Welding C-Gun Loaner forms.
3. You will receive an UPDATED FORM TO PRINT AND INCLUDE WITH THE SHIPMENT.
4. ALL SHIPMENTS must include the UPDATED FORM with SERVICE ORDER & TICKET NUMBER
5. Locate Service item # on the Service Item # Shipped for Repair lookup chart

COL Service Order Number

Ticket Number

E-Mail this completed form (and applicable Slide Rental or Welding C-Gun Loaner Form)

To: Car-O-Liner@soe.freshdesk.com

Subject: Service Order Request - Distributor - Shop - Item

All information below is required: submitted forms with missing information will be returned and cause delay.

Measuring Slide Return

☐ Empty Crate Needed for Slide Return

☑ Slide Rental Needed *(Slide Rental Form with complete address must be Included)*

Welding C-Gun Loaner

☐ Welding C-Gun Loaner Needed *(Loaner Form with complete address must be Included)*

Call Tag or Empty Crate ~ Required Information

☐ Ready for Call Tag for Pickup
☐ Confirm before issuing

Size:
Weight:
Item #:
Shipping Instructions:

Company Name: Caliber Collision 0555
Attention: Zac Madsen
Address: 3828 Louetta Road
City, ST Zip: Spring TX 77388
Phone: 281-651-1118
E-Mail (optional):

Distributor Information

Date Submitted: 09/23/2026
Distributor: CCEW
Distributor Contact: Briana Curran
Distributor Contact Phone: 972-412-5147
E-Mail: bstory@car-o-linersw.com
Collision Shop Name: Caliber Collision 0555

Ship To After Service

Company Name: Car-O-Liner Southwest
Attention: Briana Curran
Address: 3601 Executive Blvd
City/State/Zip: Mesquite TX 75149
Phone #: 972-412-5147
☐ Collect Carrier: Truck Shipment
Collect Account #:

Main Unit

Install Date is REQUIRED for Warranty Review

Main Unit Install Date: 04/21/2015
Main Unit Item #: 36424
Main Unit Serial #: 109174
Additional Details (Weld Count):

Service Item

Required Even if the Service Item is the Main Unit

Service Item # Shipped for Repair: 36424
Service Item Description: X2 slide with HMP
Service Item Serial # (if applicable):
Service Item Install Date (if different):

Problem Description

G2 sensor will not clear

Rental was picked up from Caliber 0620 (ticket 410947) and will be delivered to this center on 09/25/26.