

Veridian Petrochemicals
Bharuch Complex

Document no: TEST-C-1101-2026 Revision: A
Title: External inspection and thickness survey, C-1101
Owner: Gopal Iyer
Issued: 20 March 2026

Primary equipment: C-1101, Atmospheric column

Tester: Gopal Iyer
Equipment: C-1101

Minimum measured wall 12.8 mm at the survey points.
No active leaks, coating in sound condition.
Supports, nozzles and platforms examined.
Result: passed.