

Veridian Petrochemicals
Bharuch Complex

Document no: TEST-PSV-2101-2025 Revision: A
Title: Bench test and reset, PSV-2101
Owner: Gopal Iyer
Issued: 20 October 2025

Primary equipment: PSV-2101, Reactor relief valve 1

Tester: Gopal Iyer
Equipment: PSV-2101

Popped within tolerance of the set pressure on the third lift.
Seat tight after reset.
Seal wire and tag renewed.
Result: passed.