

Veridian Petrochemicals
Bharuch Complex

Document no: TEST-PSV-3101-2025 Revision: A
Title: Bench test and reset, PSV-3101
Owner: Gopal Iyer
Issued: 01 December 2025

Primary equipment: PSV-3101, Steam drum relief valve 1

Tester: Gopal Iyer
Equipment: PSV-3101

Popped within tolerance of the set pressure on the third lift.
Seat tight after reset.
Seal wire and tag renewed.
Result: passed.