

Veridian Petrochemicals
Bharuch Complex

Document no: TEST-PSV-3102-2025 Revision: A
Title: Bench test and reset, PSV-3102
Owner: Gopal Iyer
Issued: 18 September 2025

Primary equipment: PSV-3102, Steam drum relief valve 2

Tester: Gopal Iyer
Equipment: PSV-3102

Popped within tolerance of the set pressure on the third lift.
Seat tight after reset.
Seal wire and tag renewed.
Result: passed with an observation.